

TWR-64563

**STS-51, RSRM-033, 360T033
KSC PROCESSING CONFIGURATION
AND DATA REPORT**

9 December 1993

FINAL

Prepared for:

**NATIONAL AERONAUTICS AND SPACE ADMINISTRATION
GEORGE C. MARSHALL SPACE FLIGHT CENTER
MARSHALL SPACE FLIGHT CENTER, ALABAMA 35812**

Contract No. NAS8-38100

DR. No. 3-5

WBS.No. 4C102

***Thiokol* CORPORATION
SPACE OPERATIONS**

P.O. Box 707, Brigham City, UT 84302-0707 (801) 863-3511

N94-26153


Unclass

G3/16 0208986

(NASA-CR-193923) STS-51, RSRM-033,
360T033 KSC PROCESSING
CONFIGURATION AND DATA REPORT Final
Report (Thiokol Corp.) 104 p


STS-51, RSRM-033
KSC PROCESSING CONFIGURATION
AND DATA REPORT

Prepared by:


KSC Operations Office, Launch Support Services
Flow Lead Engineer


Approved by:


Manager, Operations Support



Manager, KSC Operations Office


Manager, Engineering Support


Systems Safety


Quality Engineering

 02 Dec 93
Project Engineer

 12-13-93
Data Management
ECS NO. SS 4796

CONTENTS

| <u>Section</u> | <u>Page</u> |
|--|-------------|
| 1.0 INTRODUCTION | 1 |
| 2.0 SUMMARY | 2 |
| 3.0 SPECIAL PROBLEMS | 3 |
| 4.0 SEGMENT/EXIT CONE RECEIPT AND INSPECTION | 4 |
| 4.1 Left Hand | 4 |
| 4.1.1 Exit Cone | 4 |
| 4.1.2 Aft Segment | 4 |
| 4.1.3 Aft Center | 4 |
| 4.1.4 Forward Center | 4 |
| 4.1.5 Forward Segment | 4 |
| 4.2 Right Hand | 5 |
| 4.2.1 Exit Cone | 5 |
| 4.2.2 Aft Segment | 5 |
| 4.2.3 Aft Center | 5 |
| 4.2.4 Forward Center | 6 |
| 4.2.5 Forward Segment | 6 |
| 5.0 AFT BOOSTER BUILD-UP | 6 |
| 5.1 Left Aft Booster | 6 |
| 5.2 Right Aft Booster | 7 |
| 6.0 SEGMENT ASSEMBLY AND CLOSEOUT | 8 |
| 6.1 Left Hand SRB Assembly | 8 |
| 6.1.1 Aft Booster to Aft Center | 8 |
| 6.1.2 Aft Center to Forward Center | 8 |
| 6.1.3 Forward Center to Forward | 8 |
| 6.1.4 Forward to Forward Assembly | 8 |
| 6.1.5 Safe and Arm Device | 8 |
| 6.2 Left Hand SRB Closeout | 9 |
| 6.2.1 Aft Joint | 9 |
| 6.2.2 Center Joint | 9 |
| 6.2.3 Forward Joint | 9 |
| 6.2.4 Forward Assembly | 9 |
| 6.2.5 Systems Tunnel | 9 |
| 6.2.6 Engineering Walkdown | 9 |
| 6.3 Right Hand SRB Assembly | 10 |
| 6.3.1 Aft Booster to Aft Center | 10 |
| 6.3.2 Aft Center to Forward Center | 10 |
| 6.3.3 Forward Center to Forward | 10 |
| 6.3.4 Forward to Forward Assembly | 10 |
| 6.3.5 Safe and Arm Device | 10 |

CONTENTS

| <u>Section</u> | <u>Page</u> |
|---|-------------|
| 6.0 SEGMENT ASSEMBLY AND CLOSEOUT (continued) | 8 |
| 6.4 Right Hand SRB Closeout | 11 |
| 6.4.1 Aft Joint | 11 |
| 6.4.2 Center Joint | 11 |
| 6.4.3 Forward Joint | 11 |
| 6.4.4 Forward Assembly | 11 |
| 6.4.5 Systems Tunnel | 11 |
| 6.4.6 Engineering Walkdown | 11 |
| 6.5 Integrated Testing and Launch | 12 |
| 6.5.1 Joint Heater Functional Test | 12 |
| 6.5.2 Shuttle Interface Test/Pad Validation Test | 12 |
| 6.5.3 Terminal Countdown Demonstration Test | 12 |
| 6.5.4 Ordinance Installation | 14 |
| 6.5.5 Countdown To Launch | 16 |
| 7.0 RECOMMENDATIONS | 26 |
| 8.0 LSS ENGINEERING AS-BUILT CONFIGURATION DATA . . . | 27 |
| 8.1 Date Segments Received at KSC | 27 |
| 8.2 Segment Offload Dates | 27 |
| 8.3 Date Exit Cone Received at KSC | 27 |
| 8.4 Offload Date of Exit Cone | 27 |
| 8.5 Mate Aft Segment to Aft Skirt (LH/RH) | 28 |
| 8.6 LH Stiffener Ring Installation | 29 |
| 8.7 RH Stiffener Ring Installation | 30 |
| 8.8 LH Splice Plate Installation | 31 |
| 8.9 RH Splice Plate Installation | 34 |
| 8.10 Exit Cone Installation (LH/RH) | 37 |
| 8.11 Exit Cone Leak Check (LH/RH) | 39 |
| 8.12 LH Field Joint Mate | 40 |
| 8.13 LH Sine Bar Data | 46 |
| 8.14 RH Field Joint Mate | 49 |
| 8.15 RH Sine Bar Data | 55 |
| 8.16 LH Joint Leak Checks & 45 Deg Plug | 58 |
| 8.17 RH Joint Leak Checks & 45 Deg Plug | 61 |
| 8.18 LH 135 Vent Plug & Leak Check | 64 |
| 8.19 RH 135 Vent Plug & Leak Check | 67 |

CONTENTS

| <u>Section</u> | <u>Page</u> |
|---|-------------|
| 8.0 LSS ENGINEERING AS-BUILT CONFIGURATION DATA . . . | 27 |
| 8.20 LH Field Joint Closeout | 70 |
| 8.21 RH Field Joint Closeout | 73 |
| 8.22 Forward Assembly Installation (LH/RH) . . . | 76 |
| 8.23 LH Safe and Arm Installation | 77 |
| 8.24 RH Safe and Arm Installation | 78 |
| 8.25 LH Verification of Leak Check/Vent Port Plug Installation | 79 |
| 8.26 RH Verification of Leak Check/Vent Port Plug Installation | 80 |
| 8.27 Roll to Pad Date | 81 |
| 8.28 Launch Date | 81 |
| 8.29 Segment Return to Utah | 81 |
| 8.30 Exit Cone Return to Utah | 81 |
| 8.31 Nozzle Return to Utah | 81 |

APPENDICES

| | | |
|------------|--|---------|
| APPENDIX A | Engineering Specifications and Changes | A1 - A2 |
| APPENDIX B | Problem Reports (PRs) | B1 - B7 |
| APPENDIX C | Motor Set Status Matrix | C1 - C2 |

1.0 INTRODUCTION

KSC Processing Configuration and Data Report is being provided as a historical document and as an enhancement to future RSRM manufacturing and processing operations. The following sections provide information on segment receipt, aft booster build up, motor assembly and closeout for STS-51, RSRM flight set 360T033.

Section 2.0 contains a summary of RSRM-033 processing. Section 3.0 discusses any significant problems or special issues that require special attention.

Sections 4.0 through 6.0 contain narrative descriptions of all key events, including any related processing problems. Appendix A provides Engineering Specifications and Changes. A list and matrix of all Problem Reports (PRs) pertinent to this flight set is provided in Appendix B. The matrix was provided by the Thiokol LSS Quality Engineering office. Copies of the PRs generated during the processing of RSRM-033 will be provided upon request. Appendix C contains the Motor Set Status matrix, which provides milestone dates for the RSRM-033 flow.

Section 7.0 provides recommendations for the improvement of flight hardware processing. Section 8.0 contains data sheets that provide flight hardware parts and consumable information installed during the booster build-up and stacking operations by location, lot/serial number, expiration and cure dates/times, and installation dates.

The postflight recovery and disassembly assessment was performed in accordance with TWR-50050B, KSC Postflight Engineering Evaluation Plan and TWR-60617, Post Flight Hardware Special Issues Report. All the information obtained during recovery and disassembly is documented in TWR-60677, KSC Ten-Day Postflight Hardware Evaluation Report.

2.0 SUMMARY

RSRM-033 flight hardware processing began in the Rotating Process & Surge Facility on February 8, 1993 with the off loading of the RH aft exit cone. The heater functional check out was completed by June 07, 1993. External tank mate was completed June 02 1993. Orbiter mate was completed on June 19, 1993. Roll to pad was accomplished on June 26, 1993. Forward skirt close outs were completed September 02, 1993. Launch took place after four attempts. Fourth and final attempt was successful on September 12, 1993.

3.0 SPECIAL PROBLEMS

The high pressure exit cone joint leak rate was 0.047 sccs. which exceeds the requirement of 0.029 sccs after the initial 30 minute time period and the extended 30 minute time period, ref. PR-AB-BI060L-0001. The trouble shooting and a low pressure deadhead tests were performed with all results nominal. Another high pressure leak test was performed and the leak rate exceeded requirements again at 0.0436 sccs. The port adapter, o-rings and seals were removed and replaced. A third high pressure leak test was performed and failed at 0.0452 sccs. The leak test tubing, port adapter, o-rings and seals were replaced once more, a low pressure dead head test and high pressure volume determination performed nominally. The joint was then pressurized for ultrasonic leak source investigation but no leaks were detected. A fourth high pressure leak test was completed and again exceeded 0.029 sccs at 0.044 sccs.

The leak test equipment was then removed and the aft exit cone assembly was demated from the nozzle. Exit cone mating flanges were photographed and inspected for contamination. Contamination was found across the secondary o-ring at 182 degrees (thought to be a hair), black fiber substances at 37, 48 and 333 degrees in the o-ring grooves and a lint fiber at the 211 degree o-ring groove during the post mate inspections. The contaminants were removed and returned to the plant for analysis.

Thiokol identified the contaminant as a synthetic fiber and believed to be inorganic, not a hair. A replacement o-ring was obtained from logistics and installed. The aft exit cone was then mated and leak checked successfully. The cause of this PR was "environmental damage" damage resulting from exposure to operational or environmental elements. No determination can be made as to how or when the joint was contaminated, but with the current operational controls, the risk of such and occurrence can only be minimized, not eliminated.

After the exit cone was de-mated new inspection steps were performed on the mating surfaces. During the metal parts inspection, raised metal was detected at 46.8 degree bolt hole edge on nozzle flange. This area was reworked on PR AB-BI060L-0002 before continuing mate operations.

Two additional problems were identified which required PR resolutions. The first was fasteners that were miss marked at various locations through out both LH/RH RSRM. MRB approval was granted to accept the improper part marking on the fasteners for use as is, ref PR SB-BI060-0003. Second was pin retainer clip elongation incorrectly checked at 1.0" and S/B at 2.0". MRB approval was granted to use as is, ref PR-SB-BI060-0004.

4.0 SEGMENT/EXIT CONE RECEIPT AND INSPECTION

4.1 Left Hand

4.1.1 Exit Cone

The aft exit cone was received at KSC on 8 Feb 1993 and off-loaded from railcar number UP57961 on 12 Feb 1993. Receiving inspection was completed on 17 Feb 1993.

4.1.2 Aft Segment

The aft segment was received at KSC on 8 Feb 1993 and off-loaded from railcar number UP50024 on 18 Feb 1993. The aft segment was mated to the aft skirt 23 Feb 1993.

4.1.3 Aft Center Segment

The aft center segment was received at KSC on 1 Mar 1993 and off-loaded from railcar number KCS10008 on 19 Mar 1993. Receiving inspection was completed on 23 Mar 1993.

4.1.4 Forward Center Segment

The forward center segment was received at KSC on 1 Mar 1993 and off-loaded from railcar number CSXT600510 on 17 Mar 1993. Receiving inspection was completed on 17 Mar 1993.

4.1.5 Forward Segment

The forward segment was received at KSC on 1 Mar 1993 and off-loaded from railcar number UP50027 on 15 Mar 1993. Receiving inspection was completed on 16 Mar 1993.

4.0 SEGMENT/EXIT CONE RECEIPT AND INSPECTION (continued)

4.2 Right Hand

4.2.1 Exit Cone

The aft exit cone was received at KSC on 1 Mar 1993 and off-loaded from railcar number UP57988 on 8 Feb 1993. Receiving inspection was completed on 9 Feb 1993.

During the receiving inspection there was a scratch identified on the bottom of the o-ring sealing surface at the 291 degree location. The anomaly was removed per SRP B-ST-0001-B, ref. PR SR-EC-60R-018-0001.

4.2.2 Aft Segment

The aft segment was received at KSC on 1 Feb 1993 and off-loaded from railcar number UP50022 on 5 Feb 1993. The aft segment was mated to the aft skirt 9 Feb 1993.

4.2.3 Aft Center

The aft center segment was received at KSC on 9 Mar 1993 and off-loaded from railcar number UP50026 on 29 Mar 1993. Receiving inspection was completed on 23 Mar 1993.

During the receiving inspection, there were three PRs generated. The first was a cut identified in the propellant grain aft surface, 210 degree, length .218", width .005", depth .125" ref. PR SR-RAC-60-008-0001. The anomaly was removed per SRP B-ST-0004-0-0. The second PR condition was identified during the ultrasonic inspection. The clevis ultrasonic unbond inspection could not be performed adequately due to extensive rework in the area aft of the pinholes. The rework resulted in a loss of signal throughout the test. A waiver (WK02808R1) to OMRSD B47SGO.051-1 was approved to accept the condition and use as is, ref. PR SR-RAC-60-008-0002. The third PR was contamination in the forward inhibitor at 170 degree location. Contamination was removed using trich and scotch brite, ref: PR SR-RAC-60-008-0003.

4.0 SEGMENT/EXIT CONE RECEIPT AND INSPECTION (continued)

4.2 Right Hand (continued)

4.2.4 Forward Center Segment

The forward center segment was received at KSC on 9 Mar 1993 and off-loaded from railcar number KCS710041 on 26 Mar 1993. Receiving inspection was completed on 30 Mar 1993.

4.2.5 Forward Segment

The forward segment was received at KSC on 9 Mar 1993 and off-loaded from railcar FEC101 on 22 Mar 1993. Receiving inspection was completed on 24 Mar 1993.

5.0 AFT BOOSTER BUILD-UP

5.1 Left Aft Booster

The aft segment was mated to the aft skirt 23 Feb 1993. Processing time was just over three weeks. Booster build was completed 19 Mar 1993.

During the high pressure exit cone leak a PR AB-BI060L-0001 was generated for leak rate exceeding the requirement. The leak rate was 0.047 sccs and should be 0.029 sccs. Contamination was found to be the cause and identified as synthetic fiber and believed to be inorganic, not hair. The joint was mated using a newly obtained o-ring from logistics.

During the remate operations raised metal was noted at the 46.8 degree bolt hole edge of the forward nozzle flange. The nick most likely happened during the demate. The raised metal was removed, ref. PR AB-BI060L-0002.

During the data review of the exit cone leak test it was determined that the 0 degree case RTD was producing incorrect values, therefore resulting in an incorrect leak rate. A recalculation of the high pressure and low pressure leak rates was performed discarding the bad RTD and evaluating the temperatures by averaging the functional RTD values for initial and final temperatures, ref. PR AB-BI060L-0004. These new values satisfy all requirements and specifications, thus no retests were required.

5.0 AFT BOOSTER BUILD-UP (continued)

5.2 Right Aft Booster

The aft segment was mated to the aft skirt 09 Feb 1993. Processing time was just over four weeks. Booster build was completed 09 Mar 1993.

During cable routing of the aft booster build process a PR was generated for not being able to verify cable was water tight at potting compound. After engineering evaluation it was determined that the cable was water tight despite the damage to molding. The cable was MRB approved for "use-as-is" condition, ref PR AB-BI060R-0002.

6.0 SEGMENT ASSEMBLY AND CLOSEOUT

The ASSEMBLY AND CLOSEOUT section is separated into three parts. The mechanical stacking and mating operation (Assembly) and the joint protection system installation (Closeout) and integrated testing and launch.

6.1 Left Hand SRB Assembly

6.1.1 Aft Booster to Aft Center

The aft booster arrived in the VAB on 10 May 1993. The aft segment was placed on the hold down posts on 10 May 1993. The aft center arrived in the VAB on the 11 May 1993 and mated to the aft on the 12 May 1993.

During the mate preps and o-ring installation, contamination was found on the clevis primary o-ring. The o-ring was removed and the groove was cleaned, regreased and a replacement o-ring installed, ref PR-SB-BI060L-0001.

6.1.2 Aft Center to Forward Center

The forward center arrived in the VAB on 13 May 1993. The forward center was mated to the aft center on 14 May 1993.

6.1.3 Forward Center to Forward

The forward arrived in the VAB on 15 May 1993. The forward was mated to the forward center on 16 May 1993.

6.1.4 Forward to Forward Assembly

The forward assembly was mated to the forward on 18 May 1993.

6.1.5 Safe and Arm Device

Safe and Arm device was installed 15 June 1993 and leak checked 17 June 1993.

6.0 SEGMENT ASSEMBLY AND CLOSEOUT (continued)

6.2 Left Hand SRB Closeout

6.2.1 Aft Joint

Leak check was completed on 15 May 1993. Incorrect GSE volumes were used to calculate leak rates. The correct volumes were calculated into the rates and found the leak rates to be acceptable, ref PR SB-BI060L-0002. Heater installation was completed on 19 May 1993. Joint close out was completed on 26 May 1993. Cable installation and heater checkout were completed 28 May 1993.

6.2.2 Center Joint

Leak check was completed on 17 May 1993. Heater installation was completed on 19 May 1993. Joint close out was completed on 22 May 1993. Cable installation and heater checkout were completed 28 May 1993.

6.2.3 Forward Joint

Leak check was completed on 19 May 1993. Low pressure primary/capture leak rate on decay exceeded requirement of between -0.0093 and 0.0082 sccs. Problem was the wrong serial numbered computer Data Acquisition System (DAS), which produced incorrect leak rates. The console was changed out and the problem corrected, ref PR SB-BI060L-0003. Heater installation was completed on 21 May 1993. Joint close out was completed on 25 May 1993. Cable installation and heater checkout were completed 28 May 1993.

6.2.4 Forward Assembly

Field joint protection installation was accomplished without any problems and completed by 24 May 1993.

During the cable routing in the forward skirt, it was noticed that the torque paint was not installed on the igniter heater assembly T-bolt band clamp. The fasteners were loosened, threads cleaned, locking compound applied and torqued to applicable requirements, ref. PR SB-BI060L-0004.

6.2.5 Systems Tunnel

Close out operations were completed without any complications on 21 June 1993.

6.2.6 Engineering Walkdown

Engineering walkdown was completed on 22 June 1993.

6.0 SEGMENT ASSEMBLY AND CLOSEOUT (continued)

6.3 Right Hand SRB Assembly

6.3.1 Aft Booster to Aft Center

The aft booster arrived in the VAB on 16 May 1993. The aft segment was placed on the hold down posts on 17 May 1993. The aft center arrived in the VAB on 18 May 1993 and mated to the aft on 20 May 1993.

6.3.2 Aft Center to Forward Center

The forward center arrived in the VAB on 20 May 1993. The forward center was mated to the aft center on 22 May 1993. Corrosion was identified on the clevis after flight grease was applied, disposition was to remove grease and corrosion and then reapply the flight grease, ref PR SB-BI060R-0002. This was accomplished without any additional problems.

6.3.3 Forward Center to Forward

The forward arrived in the VAB on 24 May 1993. The forward was mated to the forward center on 26 May 1993.

After clevis J-joint abrasion was completed, a small metallic inclusion was seen on the bonding surface. A nylon tool was used to attempt to pry the object out but was not successful. The area was wiped to remove some of the residue from the j-joint abrasion and the object could no longer be found. No measurable depth could be determined after further inspection was performed, ref PR SB-BI060R-0004. Another discrepancy was noted during mate. A nick or abrasion was seen on the secondary o-ring while performing the inspection prior to installation. Another o-ring was obtained and installed into the joint, ref PR SB-BI060R-0005. Discrepant o-ring was returned to plant for evaluation, no defect could be found during analysis.

6.3.4 Forward to Forward Assembly

The forward assembly was mated to the forward on 27 May 1993.

6.3.5 Safe and Arm Device

Safe and Arm device was installed 15 June 1993 and leak checked 17 June 1993.

6.0 SEGMENT ASSEMBLY AND CLOSEOUT (continued)

6.4 Right Hand SRB Closeout

6.4.1 Aft Joint

Leak check was completed on 21 May 1993. Heater installation was completed on 24 May 1993. Joint close out was completed on 01 June 1993. Cable installation was completed 04 June 1993. Heater checkout was completed 07 June 1993.

6.4.2 Center Joint

Leak check was completed on 25 May 1993. Heater installation was completed on 27 May 1993. Joint close out was completed on 28 May 1993. Cable installation was completed 04 June 1993. Heater checkout was completed 07 June 1993.

6.4.3 Forward Joint

Leak check was completed on 27 May 1993. Heater installation was completed on 27 May 1993. Joint close out was completed on 01 June 1993. Cable installation was completed 04 June 1993. Heater checkout was completed 07 June 1993.

6.4.4 Forward Assembly

Field joint protection installation was accomplished without any problems and completed 01 June 1993.

During the cable routing in the forward skirt, it was noticed that the torque paint was not installed on the igniter heater assembly T-bolt band clamp. The fasteners were loosened, threads cleaned, locking compound applied and torqued to applicable requirements, ref. PR SB-BI060R-0006.

6.4.5 Systems Tunnel

Close out operations were completed without any complications 21 June 1993.

6.4.6 Engineering Walkdown

Engineering walkdown was completed 22 June 1993.

6.0 SEGMENT ASSEMBLY AND CLOSEOUT (continued)

6.5 Integrated Testing and Launch

6.5.1 Joint Heater Functional Test

Igniter joint and field joint heaters were successfully tested during the SRB Electrical Check (B5307) on 9 June 1993. The performance of each heater is listed in the following table.

RSRM JOINT HEATER FUNCTIONAL TEST

| <u>Joint</u> | Primary | | | Secondary | | |
|--------------|---------------------------|----------------------------|----------------------------|---------------------------|----------------------------|----------------------------|
| | Max Vltg <u>vac</u> | Max Crnt <u>amps</u> | Max Pwr <u>watts</u> | Max Vltg <u>vac</u> | Max Crnt <u>amps</u> | Max Pwr <u>watts</u> |
| LH | | | | | | |
| IGNITER | 207.6 | 2.16 | 448 | 206.4 | 2.14 | 442 |
| FWD FJ | 206.4 | 15.68 | 3236 | 205.2 | 15.92 | 3267 |
| CTR FJ | 206.4 | 16.16 | 3335 | 205.2 | 15.84 | 3250 |
| AFT FJ | 206.4 | 16.32 | 3368 | 206.4 | 16.64 | 3434 |
| RH | | | | | | |
| IGNITER | 208.8 | 2.14 | 447 | 207.6 | 2.14 | 444 |
| FWD FJ | 206.4 | 16.00 | 3302 | 205.2 | 16.16 | 3316 |
| CTR FJ | 206.4 | 16.08 | 3319 | 206.4 | 15.60 | 3220 |
| AFT FJ | 208.8 | 16.32 | 3408 | 207.6 | 15.92 | 3305 |

6.5.2 Shuttle Interface Test/Pad Validation Test

During the Shuttle Interface Test (S0008) 21 June 1993 and Pad Validation Test conducted 27 June 1993, all GEI instruments were verified to be operational.

6.5.3 Terminal Countdown Demonstration Test

The Terminal Countdown Demonstration Test (TCDT) was conducted 01 July 1993.

During the TCDT the Operations Pressure Transducer (OPT) B47P2300C1 indicated chamber pressure drop after SRB A and B power-up. The OPT (1U77363-01) was replaced with OPT (1U77363-02). Prime Board MRB approval was granted to use the -02 OPT, ref PR-SB-BI060R-0010.

6.0 MOTOR ASSEMBLY AND CLOSEOUT (continued)

6.5 Vehicle Integration Operations (continued)

6.5.3 Terminal Countdown Demonstration Test (continued)

The Operational Pressure Transducer (OPT) 75% Simulation was conducted during the TCDT verifying proper operation of the six (6) transducer. The results are presented in the following table.

| MEASUREMENT | 75% SIM. | AMBIENT | |
|----------------|------------------|-------------|-------------|
| <u>OPT S/N</u> | <u>ID NUMBER</u> | <u>psia</u> | <u>psia</u> |
| LH | | | |
| 266 | B47P1300C | 759.8 | 12.6 |
| 269 | B47P1301C | 753.8 | 4.6 |
| 274 | B47P1302C | 761.8 | 10.6 |
| RH | | | |
| 287 | B47P2300C | 763.8 | 16.6 |
| 292 | B47P2301C | 761.8 | 12.6 |
| 295 | B47P2302C | 759.8 | 8.6 |

The OMRSD limits are: 75% Sim. 729 to 799 psia.
 Ambient -7 to 33 psia.

The joint heaters were operated during TCDT to verify their operation with pad electrical services. All voltage and current readings were similar to those experienced during electrical checkout in the VAB. The amount of time the heater were powered up is listed in the following table.

| Heater | Primary | Secondary |
|-----------------|---------------|---------------|
| <u>Location</u> | <u>HR:MIN</u> | <u>HR:MIN</u> |
| Igniters | 1:00 | 1:46 |
| Field Joints | 1:00 | 1:45 |

6.0 MOTOR ASSEMBLY AND CLOSEOUT (continued)

6.5 Vehicle Integration Operations (continued)

6.5.4 Ordinance Installation

Due to countdown scrubs and aborts it became necessary to perform the ordnance installation procedure on four occasions, 11 July, 21 July, 30 July, and 1 September. During the ordnance installation procedure (S5009) the Safe and Arm (S&A) devices were verified as operational by rotating each device from safe to armed and from armed back to safe (10) times.

The results of this verification are listed in the table below and indicate that all rotations were within the 2 second maximum rotation time requirement.

| <u>11 July</u> | <u>LH S&A</u> | <u>S/N 003</u> | <u>RH S&A</u> | <u>S/N 005</u> |
|-----------------|-------------------|----------------|-------------------|----------------|
| <u>ROTATION</u> | <u>ARM</u> | <u>SAFE</u> | <u>ARM</u> | <u>SAFE</u> |
| 1 | 0.857 | 0.937 | 0.699 | 0.817 |
| 2 | 0.817 | 0.737 | 0.697 | 0.817 |
| 3 | 0.897 | 0.897 | 0.777 | 0.777 |
| 4 | 0.737 | 0.737 | 0.817 | 0.817 |
| 5 | 0.897 | 0.776 | 0.777 | 0.817 |
| 6 | 0.696 | 0.896 | 0.776 | 0.776 |
| 7 | 0.816 | 0.896 | 0.695 | 0.776 |
| 8 | 0.696 | 0.897 | 0.776 | 0.777 |
| 9 | 0.816 | 0.777 | 0.696 | 0.857 |
| 10 | 0.817 | 0.777 | 0.857 | 0.857 |

| <u>21 July</u> | <u>LH S&A</u> | <u>S/N 003</u> | <u>RH S&A</u> | <u>S/N 005</u> |
|-----------------|-------------------|----------------|-------------------|----------------|
| <u>ROTATION</u> | <u>ARM</u> | <u>SAFE</u> | <u>ARM</u> | <u>SAFE</u> |
| 1 | 0.908 | 0.789 | 0.789 | 0.869 |
| 2 | 0.869 | 0.789 | 0.749 | 0.868 |
| 3 | 0.908 | 0.749 | 0.789 | 0.829 |
| 4 | 0.909 | 0.869 | 0.749 | 0.749 |
| 5 | 0.749 | 0.869 | 0.828 | 0.709 |
| 6 | 0.908 | 0.869 | 0.828 | 0.709 |
| 7 | 0.828 | 0.868 | 0.708 | 0.708 |
| 8 | 0.788 | 0.788 | 0.868 | 0.868 |
| 9 | 0.788 | 0.748 | 0.868 | 0.827 |
| 10 | 0.829 | 0.909 | 0.709 | 0.789 |

6.0 MOTOR ASSEMBLY AND CLOSEOUT (continued)

6.5 Vehicle Integration Operations (continued)

6.5.4 Ordinance Installation (continued)

The results of this verification are listed in the table below and indicate that all rotations were within the 2 second maximum rotation time requirement.

| <u>30 July</u> | <u>LH S&A S/N 003</u> | | <u>RH S&A S/N 005</u> | |
|-----------------|---------------------------|-------------|---------------------------|-------------|
| <u>ROTATION</u> | <u>ARM</u> | <u>SAFE</u> | <u>ARM</u> | <u>SAFE</u> |
| 1 | 0.826 | 0.846 | 0.707 | 0.829 |
| 2 | 0.747 | 0.787 | 0.827 | 0.867 |
| 3 | 0.907 | 0.747 | 0.786 | 0.827 |
| 4 | 0.746 | 0.747 | 0.827 | 0.827 |
| 5 | 0.746 | 0.866 | 0.827 | 0.747 |
| 6 | 0.746 | 0.866 | 0.827 | 0.747 |
| 7 | 0.746 | 0.747 | 0.827 | 0.826 |
| 8 | 0.827 | 0.747 | 0.707 | 0.826 |
| 9 | 0.707 | 0.866 | 0.787 | 0.746 |
| 10 | 0.866 | 0.866 | 0.747 | 0.747 |

| <u>1 September</u> | <u>LH S&A S/N 003</u> | | <u>RH S&A S/N 005</u> | |
|--------------------|---------------------------|-------------|---------------------------|-------------|
| <u>ROTATION</u> | <u>ARM</u> | <u>SAFE</u> | <u>ARM</u> | <u>SAFE</u> |
| 1 | 0.907 | 0.907 | 0.786 | 0.787 |
| 2 | 0.867 | 0.787 | 0.747 | 0.867 |
| 3 | 0.746 | 0.786 | 0.827 | 0.887 |
| 4 | 0.827 | 0.827 | 0.867 | 0.707 |
| 5 | 0.868 | 0.747 | 0.747 | 0.787 |
| 6 | 0.746 | 0.907 | 0.827 | 0.787 |
| 7 | 0.787 | 0.867 | 0.886 | 0.747 |
| 8 | 0.827 | 0.867 | 0.701 | 0.827 |
| 9 | 0.707 | 0.906 | 0.787 | 0.787 |
| 10 | 0.787 | 0.867 | 0.867 | 0.747 |

6.0 MOTOR ASSEMBLY AND CLOSEOUT (continued)

6.5 Vehicle Integration Operations (continued)

6.5.5 Countdown To Launch

The countdown to launch on 17 July was scrubbed at T-20 minutes due to a SRB hold down post PIC switch failure. The countdown was restarted at T-11 hours for a 24 July launch. This launch attempt was scrubbed at T-19 seconds due to a failure of the LH SRB APU. The countdown was started a third time at T-72 hours for a 12 August launch. This attempt was aborted at T-3 seconds when a fuel flow sensor on main engine # 2 failed to indicate proper fuel flow. The main engines were replaced and the countdown started a forth time at T-72 hours for a 12 September launch. Discovery was successfully launched 12 September at 7:45 am EDT.

The prediction of the Propellant Mean Bulk Temperature (PMBT) for the 17 July launch prepared at L-9 days was 82 degrees fahrenheit, and at L-2 days and L-24 hours was 82 degrees fahrenheit. The prediction of the Propellant Mean Bulk Temperature (PMBT) for the 24 July launch prepared at L-2 days and L-24 hours was 84 degrees fahrenheit. The prediction of the Propellant Mean Bulk Temperature (PMBT) for the 12 August launch prepared at L-7 days was 84 degrees fahrenheit, and at L-2 days and L-24 hours was 85 degrees fahrenheit. The prediction of the Propellant Mean Bulk Temperature (PMBT) for the 12 September launch prepared at L-9 days was 82 degrees fahrenheit, and at L-2 days and L-24 hours was 81 degrees fahrenheit. The post flight assessment indicates the actual PMBT at the time of launch was 80 degrees fahrenheit.

6.0 MOTOR ASSEMBLY AND CLOSEOUT (continued)

6.5 Vehicle Integration Operations (continued)

6.5.5 Countdown To Launch (continued)

Countdown #1

At approximately L-18.5 hours the igniter heaters were powered up. The field joint heaters were powered up at approximately L-11.5 hours. All heaters operated properly on their primary circuits providing operational temperature ranges of 96-101 degrees fahrenheit at the igniter joint sensors and 91-110 degrees fahrenheit at the field joint sensors. The maximum voltage supplied to the heater was 221.2 V. The ICD requirement is 208 V. nominal with limits of 191 to 225 V. The power statistics for each heater are listed in the following table.

| <u>Joint</u> | Primary | Max | Max | Secondary | Max | Max |
|--------------|------------|-------------|--------------|---------------------------------|-------------|--------------|
| | Max | Crnt | Pwr | Max | Crnt | Pwr |
| | Vltg | | | Vltg | | |
| | <u>vac</u> | <u>amps</u> | <u>watts</u> | <u>vac</u> | <u>amps</u> | <u>watts</u> |
| LH | | | | | | |
| IGNITER | 210.0 | 2.18 | 458 | Secondary circuits not used. | | |
| FWD FJ | 207.6 | 15.60 | 3239 | | | |
| CTR FJ | 202.3 | 15.28 | 3322 | | | |
| AFT FJ | 208.8 | 16.32 | 3408 | | | |
| RH | | | | | | |
| IGNITER | 211.0 | 2.14 | 451 | Secondary circuits not used. | | |
| FWD FJ | 207.6 | 15.68 | 3302 | | | |
| CTR FJ | 207.6 | 15.68 | 3355 | | | |
| AFT FJ | 210.0 | 15.16 | 3355 | | | |

The igniter heaters were activated at 197:18:49 GMT (07-16-93, 14:49 EDT), and were deactivated following the countdown scrub at 198:14:18 GMT (07-17-93, 10:18 EDT). The total activation time was 19 hours and 19 minutes, and power was applied to the heating elements an average of 28% of that time after the initial warm up. The field joint heaters were activated at 198:01:54 GMT (07-16-93, 21:54 EDT), and were deactivated after the scrub at 198:14:18 GMT (07-17-93, 10:18 EDT). The total activation time was 12 hours and 24 minutes, and power was applied to the heating elements an average of 17% of the time after the initial warm up.

6.0 MOTOR ASSEMBLY AND CLOSEOUT (continued)

6.5 Vehicle Integration Operations (continued)

6.5.5 Countdown To Launch (continued)

Countdown #1 (continued)

| MEASUREMENT | 75% SIM. | AMBIENT | |
|----------------|------------------|-------------|-------------|
| <u>OPT S/N</u> | <u>ID NUMBER</u> | <u>psia</u> | <u>psia</u> |
| LH | | | |
| 266 | B47P1300C | 759.8 | 10.6 |
| 269 | B47P1301C | 753.8 | 2.6 |
| 274 | B47P1302C | 763.8 | 12.6 |
| RH | | | |
| 287 | B47P2300C | 769.8 | 16.6 |
| 292 | B47P2301C | 759.8 | 12.6 |
| 295 | B47P2302C | 759.8 | 8.6 |

The OMRSD limits are: 75% Sim. 729 to 799 psia.
 Ambient -7 to 33 psia.

The countdown was scrubbed at T-20 minutes. The S&A's were not rotated.

Countdown #2

At approximately L-18 hours the igniter heaters were powered up. The field joint heaters were powered up at approximately L-11.5 hours. All heaters operated properly on their primary circuits providing operational temperature ranges of 97-101 degrees fahrenheit at the igniter joint sensors and 91-107 degrees fahrenheit at the field joint sensors. The maximum voltage supplied to the heater was 211.2 V. The ICD requirement is 208 V. nominal with limits of 191 to 225 V. The power statistics for each heater are listed in the following table.

| <u>Joint</u> | Primary | | | Secondary | | |
|--------------|---------------------------|----------------------------|----------------------------|---------------------------------|----------------------------|----------------------------|
| | Max Vltg <u>vac</u> | Max Crnt <u>amps</u> | Max Pwr <u>watts</u> | Max Vltg <u>vac</u> | Max Crnt <u>amps</u> | Max Pwr <u>watts</u> |
| LH | | | | | | |
| IGNITER | 211.2 | 2.18 | 460 | Secondary circuits not used. | | |
| FWD FJ | 208.6 | 15.68 | 3239 | | | |
| CTR FJ | 208.8 | 16.00 | 3324 | | | |
| AFT FJ | 210.0 | 16.24 | 3410 | | | |

Thiokol CORPORATION
SPACE OPERATIONS

6.0 MOTOR ASSEMBLY AND CLOSEOUT (continued)

6.5 Vehicle Integration Operations (continued)

6.5.5 Countdown To Launch (continued)

Countdown #2 (continued)

| <u>Joint</u> | Primary | | | Secondary | | |
|--------------|---------------------------|----------------------------|----------------------------|---------------------------|----------------------------|----------------------------|
| | Max Vltg <u>vac</u> | Max Crnt <u>amps</u> | Max Pwr <u>watts</u> | Max Vltg <u>vac</u> | Max Crnt <u>amps</u> | Max Pwr <u>watts</u> |
| RH | | | | | | |
| IGNITER | 211.2 | 2.18 | 460 | Secondary | circuits | |
| FWD FJ | 208.8 | 16.16 | 3355 | not used. | | |
| CTR FJ | 208.8 | 16.00 | 3302 | | | |
| AFT FJ | 210.0 | 16.24 | 3391 | | | |

The igniter heaters were activated at 204:19:14 GMT (07-23-93, 15:14 EDT), and were deactivated at the end of the T-9 minute hold which was 205:13:18 GMT (07-24-93, 09:18 EDT). The total activation time was 18 hours and 04 minutes, and power was applied to the heating elements an average of 31% of that time after the initial warm up. The field joint heaters were activated at 205:01:52 GMT (07-23-93, 21:52 EDT), and were deactivated at about T-1 minute which was 205:13:27 GMT (07-24-93, 09:27 EDT). The total activation time was 11 hours and 35 minutes, and power was applied to the heating elements an average of 19% of the time after the initial warm up.

At about T-1.5 hr in the countdown to OPT 75% SIM was conducted. All OPT readings were within required limits as shown below.

| MEASUREMENT | 75% SIM. | AMBIENT | |
|----------------|------------------|-------------|-------------|
| <u>OPT S/N</u> | <u>ID NUMBER</u> | <u>psia</u> | <u>psia</u> |
| LH | | | |
| 266 | B47P1300C | 759.8 | 10.6 |
| 269 | B47P1301C | 753.8 | 4.6 |
| 274 | B47P1302C | 761.8 | 12.6 |
| RH | | | |
| 287 | B47P2300C | 761.8 | 14.6 |
| 292 | B47P2301C | 761.8 | 12.6 |
| 295 | B47P2302C | 759.8 | 8.6 |

The OMRSD limits are: 75% Sim. 729 to 799 psia.
Ambient -7 to 33 psia.

6.0 MOTOR ASSEMBLY AND CLOSEOUT (continued)

6.5 Vehicle Integration Operations (continued)

6.5.5 Countdown To Launch (continued)

Countdown #2 (continued)

The Safe and Arm devices were successfully rotated to armed at T-5 minutes then rotated back to safe immediately following the countdown scrub.

| | | | | |
|------------|-----|------|------|------|
| Left Hand | Arm | 0.89 | Safe | 0.81 |
| Right Hand | Arm | 0.93 | Safe | 0.81 |

The countdown scrub was scrubbed at T-19 seconds.

Countdown #3

At approximately L-18 hours the igniter heater were powered up. The field joint heater were powered up at approximately L-11.5 hours. All heaters operated properly on their primary circuits, except the left aft heater which experienced at controller problem and was operated on the secondary circuit. The heaters provided operational temperature ranges of 97-101 degrees fahrenheit at the igniter joint sensors and 93-106 degrees fahrenheit at the field joint sensors. The maximum voltage supplied to the heater was 210.0 V. The ICD requirement is 208 V. nominal with limits of 191 to 225 V. The power statistics for each heater are listed in the following table.

| | Primary | | | Secondary | | |
|--------------|------------|-------------|--------------|--------------------|-------------|--------------|
| | Max | Max | Max | Max | Max | Max |
| | Vltg | Crnt | Pwr | Vltg | Crnt | Pwr |
| <u>Joint</u> | <u>vac</u> | <u>amps</u> | <u>watts</u> | <u>vac</u> | <u>amps</u> | <u>watts</u> |
| LH | | | | | | |
| IGNITER | 210.0 | 2.14 | 455 | | | |
| FWD FJ | 208.8 | 16.00 | 3286 | | | |
| CTR FJ | 208.8 | 16.32 | 3371 | | | |
| AFT FJ | | | | 208.8 | 16.64 | 3454 |
| RH | | | | | | |
| IGNITER | 210.0 | 2.16 | 454 | Secondary circuits | | |
| FWD FJ | 208.8 | 15.84 | 3291 | not used. | | |
| CTR FJ | 208.8 | 16.00 | 3341 | | | |
| AFT FJ | 210.0 | 16.32 | 3408 | | | |

6.0 MOTOR ASSEMBLY AND CLOSEOUT (continued)

6.5 Vehicle Integration Operations (continued)

6.5.5 Countdown To Launch (continued)

Countdown #3 (continued)

The igniter heaters were activated at 223:18:58 GMT (08-12-93, 14:58 EDT), and were deactivated at the end of the T-9 minute hold which was 224:13:01 GMT (08-12-93, 09:01 EDT). The total activation time was 18 hours and 03 minutes, and power was applied to the heating elements an average of 33% of that time after the initial warm up. The field joint heaters were activated at 224:01:43 GMT (08-12-93, 21:43 EDT), and were deactivated at about T-1 minute which was 224:13:12 GMT (08-12-93, 09:12 EDT). The total activation time was 11 hours and 29 minutes, and power was applied to the heating elements an average of 18% of the time after the initial warm up.

IPR 51V-109 was written describing the left aft heater activation problem and was assigned to Lockheed MLP/GSE for disposition. The problem was in the MLP control panel interface for the heaters.

At about T-1.5 hr in the countdown to OPT 75% SIM was conducted. All OPT readings were within required limits as shown below.

| MEASUREMENT | 75% SIM. | AMBIENT | |
|----------------|------------------|-------------|-------------|
| <u>OPT S/N</u> | <u>ID NUMBER</u> | <u>psia</u> | <u>psia</u> |
| LH | | | |
| 266 | B47P1300C | 759.8 | 12.6 |
| 269 | B47P1301C | 753.8 | 4.6 |
| 274 | B47P1302C | 761.8 | 10.6 |
| RH | | | |
| 287 | B47P2300C | 763.8 | 16.6 |
| 292 | B47P2301C | 761.8 | 12.6 |
| 295 | B47P2302C | 759.8 | 8.6 |

The OMRSD limits are: 75% Sim. 729 to 799 psia.
 Ambient -7 to 33 psia.

The Safe and Arm devices were successfully rotated to armed at T-5 minutes then rotated back to safe immediately following the main engine shutdown and launch abort.

| | | | | |
|------------|-----|------|------|------|
| Left Hand | Arm | 0.85 | Safe | 0.89 |
| Right Hand | Arm | 0.93 | Safe | 0.89 |

6.0 MOTOR ASSEMBLY AND CLOSEOUT (continued)

6.5 Vehicle Integration Operations (continued)

6.5.5 Countdown To Launch (continued)

Countdown #3 (continued)

The launch was aborted T-3 seconds.

Following the launch abort, the left aft heater controller was changed out and the heater functionality test was rerun. All heaters performed properly on both primary and secondary circuits.

Lightning struck the water tower or near the water tower on 9 September 1993 which caused damaged to some pad electrical systems. Several systems were retested to ensure the integrity of the circuitry, including the joint heating system, OPT's and GEI instrumentation. Another heater functionality test was conducted verifying that no damage was sustained within the joint heating system. All instrumentation was verified as operational.

Countdown #4

At approximately T-27 hours the option to rotated the S&A's was exercised due to uncertainties expressed since the lightning strike. The S&A's were rotated from safe to armed and armed back to safe on time. The times for S&A rotation to armed are as follows:

| | | | | |
|------------|-----|------|------|------|
| Left Hand | Arm | 0.79 | Safe | 0.75 |
| Right Hand | Arm | 0.87 | Safe | 0.83 |

At approximately L-18 hours the igniter heater were powered up. The field joint heater were powered up at approximately L-11.5 hours. All heaters operated properly on their primary circuits providing operational temperature ranges of 97-101 degrees fahrenheit at the igniter joint sensors and 91-106 degrees fahrenheit at the field joint sensors. The maximum voltage supplied to the heater was 210.0 V. The ICD requirement is 208 V. nominal with limits of 191 to 225 V. The power statistics for each heater are listed in the following table.

6.0 MOTOR ASSEMBLY AND CLOSEOUT (continued)

6.5 Vehicle Integration Operations (continued)

6.5.5 Countdown To Launch (continued)

Countdown #4 (continued)

| <u>Joint</u> | Primary | Max | Max | Secondary | Max | Max |
|--------------|---------------------------|---------------------|---------------------|---------------------------------|---------------------|---------------------|
| | Max Vltg <u>vac</u> | Crnt <u>amps</u> | Pwr <u>watts</u> | Max Vltg <u>vac</u> | Crnt <u>amps</u> | Pwr <u>watts</u> |
| LH | | | | Secondary circuits not used. | | |
| IGNITER | 210.0 | 2.18 | 455 | | | |
| FWD FJ | 208.8 | 15.68 | 3239 | | | |
| CTR FJ | 208.8 | 16.16 | 3335 | | | |
| AFT FJ | 210.0 | 16.24 | 3491 | | | |
| RH | | | | Secondary circuits not used. | | |
| IGNITER | 210.0 | 2.18 | 455 | | | |
| FWD FJ | 207.6 | 16.16 | 3335 | | | |
| CTR FJ | 207.6 | 15.76 | 3255 | | | |
| AFT FJ | 210.0 | 16.24 | 3391 | | | |

The igniter heaters were activated at 254:17:31 GMT (09-12-93 13:31 EDT), and were deactivated at the end of the T-9 minute hold which was 255:11:36 GMT (09-12-93 07:36 EDT). The total activation time was 18 hours and 1 minutes, and power was applied to the heating elements an average of 35% of that time after the initial warm up. The field joint heaters were activated at 255:00:15 GMT (09-12-93 21:15 EDT), and were deactivated at about T-1 minutes which was 255:11:45 GMT (09-12-93 07:45 EDT). The total activation time was 11 hours and 30 minutes, and power was applied to the heating elements an average of 21% of the time after the initial warm up.

6.0 MOTOR ASSEMBLY AND CLOSEOUT (continued)

6.5 Vehicle Integration Operations (continued)

6.5.5 Countdown To Launch (continued)

Countdown #4 (continued)

At about T-1.5 hr in the countdown to OPT 75% SIM was conducted. All OPT readings were within required limits as shown below.

| MEASUREMENT | 75% SIM. | AMBIENT | |
|----------------|------------------|-------------|-------------|
| <u>OPT S/N</u> | <u>ID NUMBER</u> | <u>psia</u> | <u>psia</u> |
| LH | | | |
| 266 | B47P1300C | 759.8 | 10.6 |
| 269 | B47P1301C | 753.8 | 2.6 |
| 274 | B47P1302C | 761.8 | 12.6 |
| RH | | | |
| 287 | B47P2300C | 763.8 | 14.6 |
| 292 | B47P2301C | 761.8 | 12.6 |
| 295 | B47P2302C | 759.8 | 8.6 |

The OMRSD limits are: 75% Sim. 729 to 799 psia.
 Ambient -7 to 33 psia.

The S&A rotation times at T-5 minutes were:

| | | | |
|---------------|------|----------------|------|
| Left Hand S&A | 0.97 | Right Hand S&A | 0.85 |
|---------------|------|----------------|------|

The Nozzle/Case Joint temperature ranged from 78 to 83 degrees fahrenheit during the LCC time period. The Flex Bearing Mean Bulk Temperature (FBMBT) at the time of launch was 81 degrees fahrenheit. The Aft Skirt GN2 purge was initiated at 254:22:30 GMT (09-11-93 18:30 EDT) at high temperature, low flow for 31 minutes to verify proper purge operation. The purge was again initiated at 255:11:20 GMT (09-12-93), successfully T-15 minutes, using high flow rate and high temperature to perform the aft skirt hydrazine cleansing purge. Total aft skirt purge activation time was approximately 56 minutes.

The case acreage temperatures for the LCC instruments located at 270 degrees ranged from 74 to 80 degrees fahrenheit.

6.0 MOTOR ASSEMBLY AND CLOSEOUT (continued)

6.5 Vehicle Integration Operations (continued)

6.5.5 Countdown To Launch (continued)

Countdown #4 (continued)

The ambient temperature was 71 to 75 degrees fahrenheit during the Terminal countdown and was 73 degrees fahrenheit at launch.

There were no Launch Commit Criteria (LCC) violations from RSRM hardware during the countdown activities.

STS-51 was successfully launched on Sunday, 12 September 1993, at 255:11:45:00.007 GMT which was 0745 hours EDT.

7.0 RECOMMENDATIONS

No recommendations are made at this time.

8.0 LSS ENGINEERING AS-BUILT CONFIGURATION DATA

RSRM: 033 BIO: 60 STS: 58

8.1 Date Segments Received at KSC

| | <u>AFT</u> | <u>AFT CENTER</u> | <u>FWD CENTER</u> | <u>FORWARD</u> |
|-----------|------------|-------------------|-------------------|----------------|
| LH: DATE | 08FEB93 | 01MAR93 | 11MAR93 | 01MAR93 |
| P/N: | 1U76757-10 | 1U76792-05 | 1U76791-05 | 1U76790-13 |
| S/N: | 0000001 | 0000008 | 0000008 | 0000008 |
| R/R CAR # | UP50024 | KCS710008 | CSXT600510 | UP50027 |
| | | | | |
| RH: DATE | 01MAR93 | 09MAR93 | 09MAR93 | 09MAR93 |
| P/N: | 1U76958-11 | 1U76792-06 | 1U76791-06 | 1U76790-14 |
| S/N: | 0000001 | 0000008 | 0000008 | 0000014 |
| R/R CAR # | UP50022 | UP50026 | KCS710041 | FEC101 |

8.2 Segment Offload Dates

| | | | | |
|-----|---------|---------|---------|---------|
| LH: | 18FEB93 | 19MAR93 | 17MAR93 | 15MAR93 |
| RH: | 08MAR93 | 14APR93 | 26MAR93 | 22MAR93 |

8.3 Date Exit Cone Received at KSC

| | <u>DATE</u> | <u>PART NO.</u> | <u>SERIAL NO.</u> | <u>R/R CAR #</u> |
|-----|-------------|-----------------|-------------------|------------------|
| LH: | 08FEB93 | 1U76970-01 | 0000017 | UP57961 |
| RH: | 01MAR93 | 1U76970-02 | 0000018 | UP57988 |

8.4 Offload Date of Exit Cone

| | | | |
|-----|---------|-----|---------|
| LH: | 12FEB93 | RH: | 08MAR93 |
|-----|---------|-----|---------|

8.0 LSS ENGINEERING AS-BUILT CONFIGURATION DATA (cont.)

RSRM: 033 BIO: 60 STS: 58

8.5 Mate Aft Segment to Aft Skirt (LH/RH)

| <u>LH AFT</u> | | | |
|-----------------|-----------------|-------------------|---------------|
| | <u>PART NO.</u> | <u>SERIAL NO.</u> | <u>DATE</u> |
| | 1U76957-01 | 0000001 | 23FEB93 |
| <u>ITEM</u> | <u>PART NO.</u> | <u>LOT NO.</u> | <u>QTY</u> |
| PINS | 1U51055-02 | ECL-0006 | 176 |
| | | ECL-0003 | 1 |
| <u>LOCATION</u> | <u>DATE</u> | <u>TIME</u> | <u>DEGREE</u> |
| FIRST PIN: | 23FEB93 | 03:30 | 290 |
| LAST PIN: | 23FEB93 | 03:45 | 110 |

AFT SEGMENT/SKIRT CLOSEOUT:

| <u>ITEM</u> | <u>PART NO.</u> | <u>SERIAL/LOT NUMBER</u> |
|-------------------------|-----------------|--------------------------|
| FIELD JOINT KIT (STRAP) | 1U75345-07 | 0000181 |
| INSULATOR | 1U50746-03 | 0141 |
| ADHESIVE | STW5-3837 | 0023 |

=====

RH AFT

| | <u>PART NO.</u> | <u>SERIAL NO.</u> | <u>DATE</u> |
|-----------------|-----------------|-------------------|---------------|
| | 1U76958-11 | 0000001 | 09MAR93 |
| <u>ITEM</u> | <u>PART NO.</u> | <u>LOT NO.</u> | <u>QTY</u> |
| PINS | 1U51055-02 | ECL-0001 | 84 |
| | | ECL-0003/0006 | 79/14 |
| <u>LOCATION</u> | <u>DATE</u> | <u>TIME</u> | <u>DEGREE</u> |
| FIRST PIN: | 09MAR93 | 23:00 | 36 |
| LAST PIN: | 09MAR93 | 23:21 | 196 |

AFT SEGMENT/SKIRT CLOSEOUT:

| <u>ITEM</u> | <u>PART NO.</u> | <u>SERIAL/LOT NUMBER</u> |
|-------------------------|-----------------|--------------------------|
| FIELD JOINT KIT (STRAP) | 1U75345-07 | 0000165 |
| INSULATOR | 1U50746-03 | ECL-0140 |
| ADHESIVE | STW5-3837 | ECL-0024 |

8.0 LSS ENGINEERING AS-BUILT CONFIGURATION DATA (cont.)

RSRM: 033 BIO: 60 STS: 58

8.6 LH Stiffener Ring Installation

| <u>LOCATION</u> | <u>PART NO.</u> | <u>SERIAL/LOT NUMBER</u> | <u>DATE</u> |
|-----------------|-----------------|----------------------------|-------------|
| FWD RING, INSUL | 1U52501-01 | 0000314 | 24FEB93 |
| FWD RING | 1U52502-04 | 0000257 | 24FEB93 |
| FWD RING, INSUL | 1U52501-04 | 0000213 | 24FEB93 |
| FWD RING | 1U52502-07 | 0000244 | 24FEB93 |
| FWD RING, INSUL | 1U52501-05 | 0000213 | 24FEB93 |
| FWD RING | 1U52502-08 | 0000243 | 24FEB93 |
| BOLT | 1U52510-01 | ECL-0016 | 24FEB93 |
| MID RING, INSUL | 1U52501-01 | 0000313 | 24FEB93 |
| MID RING | 1U52502-04 | 0000258 | 24FEB93 |
| MID RING, INSUL | 1U52501-04 | 0000212 | 24FEB93 |
| MID RING | 1U52502-07 | 0000245 | 24FEB93 |
| MID RING, INSUL | 1U52501-05 | 0000212 | 24FEB93 |
| MID RING | 1U52502-08 | 0000244 | 24FEB93 |
| BOLT | 1U52510-01 | ECL-0016/0021 164/13 ea | 24FEB93 |
| AFT RING, INSUL | 1U52501-01 | 0000316 | 24FEB93 |
| AFT RING | 1U52502-04 | 0000259 | 24FEB93 |
| AFT RING, INSUL | 1U52501-04 | 0000215 | 24FEB93 |
| AFT RING | 1U52502-07 | 0000246 | 24FEB93 |
| AFT RING, INSUL | 1U52501-05 | 0000215 | 24FEB93 |
| AFT RING | 1U52502-08 | 0000245 | 24FEB93 |
| BOLT | 1U52510-01 | ECL-0016 | 24FEB93 |

8.0 LSS ENGINEERING AS-BUILT CONFIGURATION DATA (cont.)

RSRM: 033 BIO: 60 STS: 58

8.7 RH Stiffener Ring Installation

| <u>LOCATION</u> | <u>PART NO.</u> | <u>SERIAL/LOT NUMBER</u> | <u>DATE</u> |
|-----------------|-----------------|--------------------------|-------------|
| FWD RING, INSUL | 1U52501-01 | 0000317 | 15MAR93 |
| FWD RING | 1U52502-04 | 0000243 | 15MAR93 |
| FWD RING, INSUL | 1U52501-04 | 0000216 | 15MAR93 |
| FWD RING | 1U52502-07 | 0000230 | 15MAR93 |
| FWD RING, INSUL | 1U52501-05 | 0000217 | 15MAR93 |
| FWD RING | 1U52502-08 | 0000232 | 15MAR93 |
| BOLT | 1U52510-01 | ECL-0010/0016 | 15MAR93 |
| MID RING, INSUL | 1U52501-01 | 0000315 | 15MAR93 |
| MID RING | 1U52502-04 | 0000253 | 15MAR93 |
| MID RING, INSUL | 1U52501-04 | 0000214 | 15MAR93 |
| MID RING | 1U52502-07 | 0000241 | 15MAR93 |
| MID RING, INSUL | 1U52501-05 | 0000214 | 15MAR93 |
| MID RING | 1U52502-08 | 0000234 | 15MAR93 |
| BOLT | 1U52510-01 | ECL-0016 | 15MAR93 |
| AFT RING, INSUL | 1U52501-01 | 0000318 | 15MAR93 |
| AFT RING | 1U52502-04 | 0000246 | 15MAR93 |
| AFT RING, INSUL | 1U52501-04 | 0000217 | 15MAR93 |
| AFT RING | 1U52502-07 | 0000233 | 15MAR93 |
| AFT RING, INSUL | 1U52501-05 | 0000216 | 15MAR93 |
| AFT RING | 1U52502-08 | 0000250 | 15MAR93 |
| BOLT | 1U52510-01 | ECL-0016 | 15MAR93 |

8.0 LSS ENGINEERING AS-BUILT CONFIGURATION DATA (cont.)

RSRM: 033 BIO: 60 STS: 58

8.8 LH Splice Plate Installation

FORWARD STIFFENER RING

| <u>ITEM</u> | <u>LOCATION</u> | <u>PART NO.</u> | <u>SERIAL/LOT NO.</u> |
|--------------------|-----------------|-----------------|-----------------------|
| PLATE | 210 | 1U52508-01 | 0000580 |
| BOLT, SHOULDER | 210 | 1U52734-02 | ECL-0023 |
| PLATE | 330 | 1U52508-01 | 0000581 |
| BOLT, SHOULDER | 330 | 1U52734-02 | ECL-0023 |
| SPLICE PLATE | 210 | 1U52506-02 | 0000589 |
| BOLT, SHOULDER | 210 | 1U52734-03 | ECL-0012 |
| SPLICE PLATE | 330 | 1U52506-02 | 0000585 |
| BOLT, SHOULDER | 330 | 1U52734-03 | ECL-0012 |
| SPLICE PLATE | 90 | 1U52506-03 | 0000198 |
| BOLT, SHOULDER | 90 | 1U52734-04 | ECL-0005 |
| ADAPT PLATE, UPPER | 90 | 1U77164-01 | 0000214 |
| ADAPT PLATE, LOWER | 90 | 1U77164-01 | 0000215 |
| BOLT, SHOULDER | 90 | 1U52734-01 | ECL-0014 |

8.0 LSS ENGINEERING AS-BUILT CONFIGURATION DATA (cont.)

RSRM: 033 BIO: 60 STS: 58

8.8 LH Splice Plate Installation (continued)

CENTER STIFFENER RING

| <u>ITEM</u> | <u>LOCATION</u> | <u>PART NO.</u> | <u>SERIAL/LOT NO.</u> |
|--------------------|-----------------|-----------------|-----------------------|
| PLATE | 210 | 1U52508-01 | 0000582 |
| BOLT, SHOULDER | 210 | 1U52734-02 | ECL-0023 |
| PLATE | 330 | 1U52508-01 | 0000584 |
| BOLT, SHOULDER | 330 | 1U52734-02 | ECL-0023 |
| SPLICE PLATE | 210 | 1U52506-02 | 0000586 |
| BOLT, SHOULDER | 210 | 1U52734-03 | ECL-0012 |
| SPLICE PLATE | 330 | 1U52506-02 | 0000582 |
| BOLT, SHOULDER | 330 | 1U52734-03 | ECL-0012 |
| SPLICE PLATE | 90 | 1U52506-03 | 0000199 |
| BOLT, SHOULDER | 90 | 1U52734-04 | ECL-0005 |
| ADAPT PLATE, UPPER | 90 | 1U77164-01 | 0000213 |
| ADAPT PLATE, LOWER | 90 | 1U77164-01 | 0000212 |
| BOLT, SHOULDER | 90 | 1U52734-01 | ECL-0004 |

8.0 LSS ENGINEERING AS-BUILT CONFIGURATION DATA (cont.)

RSRM: 033 BIO: 60 STS: 58

8.8 LH Splice Plate Installation (continued)

AFT STIFFENER RING

| <u>ITEM</u> | <u>LOCATION</u> | <u>PART NO.</u> | <u>SERIAL/LOT NO.</u> |
|--------------------|-----------------|-----------------|-----------------------|
| PLATE | 210 | 1U52508-01 | 0000579 |
| BOLT, SHOULDER | 210 | 1U52734-02 | ECL-0023 |
| PLATE | 330 | 1U52508-01 | 0000583 |
| BOLT, SHOULDER | 330 | 1U52734-02 | ECL-0023 |
| SPLICE PLATE | 210 | 1U52506-02 | 0000583 |
| BOLT, SHOULDER | 210 | 1U52734-03 | ECL-0012 |
| SPLICE PLATE | 330 | 1U52506-02 | 0000581 |
| BOLT, SHOULDER | 330 | 1U52734-03 | ECL-0012 |
| SPLICE PLATE | 90 | 1U52506-03 | 0000197 |
| BOLT, SHOULDER | 90 | 1U52734-04 | ECL-0005 |
| ADAPT PLATE, UPPER | 90 | 1U77164-01 | 0000216 |
| ADAPT PLATE, LOWER | 90 | 1U77164-01 | 0000217 |
| BOLT, SHOULDER | 90 | 1U52734-01 | ECL-0014 |

8.0 LSS ENGINEERING AS-BUILT CONFIGURATION DATA (cont.)

RSRM: 033 BIO: 60 STS: 58

8.9 RH Splice Plate Installation

FORWARD STIFFENER RING

| <u>ITEM</u> | <u>LOCATION</u> | <u>PART NO.</u> | <u>SERIAL/LOT NO.</u> |
|--------------------|-----------------|-----------------|-----------------------|
| PLATE | 210 | 1U52508-01 | 0000609 |
| BOLT, SHOULDER | 210 | 1U52734-02 | ECL-0023 |
| PLATE | 330 | 1U52508-01 | 0000608 |
| BOLT, SHOULDER | 330 | 1U52734-02 | ECL-0023 |
| SPLICE PLATE | 210 | 1U52506-02 | 0000584 |
| BOLT, SHOULDER | 210 | 1U52734-03 | ECL-0005 |
| SPLICE PLATE | 330 | 1U52506-02 | 0000592 |
| BOLT, SHOULDER | 330 | 1U52734-03 | ECL-0005 |
| SPLICE PLATE | 90 | 1U52506-03 | 0000211 |
| BOLT, SHOULDER | 90 | 1U52734-04 | ECL-0001 |
| ADAPT PLATE, UPPER | 90 | 1U77164-01 | 0000219 |
| ADAPT PLATE, LOWER | 90 | 1U77164-01 | 0000211 |
| BOLT, SHOULDER | 90 | 1U52734-01 | ECL-0014 |

8.0 LSS ENGINEERING AS-BUILT CONFIGURATION DATA (cont.)

RSRM: 033 BIO: 60 STS: 58

8.9 RH Splice Plate Installation (continued)

CENTER STIFFENER RING

| <u>ITEM</u> | <u>LOCATION</u> | <u>PART NO.</u> | <u>SERIAL/LOT NO.</u> |
|--------------------|-----------------|-----------------|-----------------------|
| PLATE | 210 | 1U52508-01 | 0000607 |
| BOLT, SHOULDER | 210 | 1U52734-02 | ECL-0023 |
| PLATE | 330 | 1U52508-01 | 0000586 |
| BOLT, SHOULDER | 330 | 1U52734-02 | ECL-0023 |
| SPLICE PLATE | 210 | 1U52506-02 | 0000590 |
| BOLT, SHOULDER | 210 | 1U52734-03 | ECL-0005 |
| SPLICE PLATE | 330 | 1U52506-02 | 0000587 |
| BOLT, SHOULDER | 330 | 1U52734-03 | ECL-0005 |
| SPLICE PLATE | 90 | 1U52506-03 | 0000212 |
| BOLT, SHOULDER | 90 | 1U52734-04 | ECL-0001 |
| ADAPT PLATE, UPPER | 90 | 1U77164-01 | 0000221 |
| ADAPT PLATE, LOWER | 90 | 1U77164-01 | 0000210 |
| BOLT, SHOULDER | 90 | 1U52734-01 | ECL-0014 |

8.0 LSS ENGINEERING AS-BUILT CONFIGURATION DATA (cont.)

RSRM: 033 BIO: 60 STS: 58

8.9 RH Splice Plate Installation (continued)

AFT STIFFENER RING

| <u>ITEM</u> | <u>LOCATION</u> | <u>PART NO.</u> | <u>SERIAL/LOT NO.</u> |
|--------------------|-----------------|-----------------|-----------------------|
| PLATE | 210 | 1U52508-01 | 0000585 |
| BOLT, SHOULDER | 210 | 1U52734-02 | ECL-0023 |
| PLATE | 330 | 1U52508-01 | 0000610 |
| BOLT, SHOULDER | 330 | 1U52734-02 | ECL-0023 |
| SPLICE PLATE | 210 | 1U52506-02 | 0000588 |
| BOLT, SHOULDER | 210 | 1U52734-03 | ECL-0005 |
| SPLICE PLATE | 330 | 1U52506-02 | 0000591 |
| BOLT, SHOULDER | 330 | 1U52734-03 | ECL-0005 |
| SPLICE PLATE | 90 | 1U52506-03 | 0000200 |
| BOLT, SHOULDER | 90 | 1U52734-04 | ECL-0001 |
| ADAPT PLATE, UPPER | 90 | 1U77164-01 | 0000218 |
| ADAPT PLATE, LOWER | 90 | 1U77164-01 | 0000220 |
| BOLT, SHOULDER | 90 | 1U52734-01 | ECL-0004 |

8.0 LSS ENGINEERING AS-BUILT CONFIGURATION DATA (cont.)

RSRM: 033 BIO: 60 STS: 58

8.10 Exit Cone Installation (LH/RH)

LH: First mate

| <u>ITEM</u> | <u>PART NO.</u> | <u>SERIAL/LOT NO.</u> | <u>DATE</u> | <u>EXP DATE</u> |
|--------------|-----------------|-----------------------|-------------|-----------------|
| EXIT CONE | 1U76970-01 | 0000017 | 25/FEB93 | N/A |
| GREASE | 1U51916-09 | ECL-0072 | 24FEB93 | 20AUG94 |
| O-RING, PRI | 1U75801-03 | 0000374 | *25FEB93 | 02AUG93 |
| O-RING, SEC | 1U75801-04 | 0000374 | *25FEB93 | 26MAR93 |
| Backfill RTV | STW5-2813 | ECL- N/A | N/A | N/A |
| BOLT | 1U75756-10 | ECL-0019 | 25FEB93 | N/A |

REMARKS: During the high pressure leak check there was a failure rate of 0.0427 sccs. Maximum allowable is 0.029 sccs. Demate was required.

RH:

| <u>ITEM</u> | <u>PART NO.</u> | <u>SERIAL/LOT NO.</u> | <u>DATE</u> | <u>EXP DATE</u> |
|-------------|-----------------|-----------------------|-------------|-----------------|
| EXIT CONE | 1U76970-02 | 0000018 | 23MAR93 | N/A |
| GREASE | 1U51916-09 | ECL-0075 | 23MAR93 | 10MAR95 |
| O-RING, PRI | 1U75801-03 | 0000375 | *23MAR93 | 04AUG93 |
| O-RING, SEC | 1U75801-04 | 0000374 | *23MAR93 | 05SEP93 |
| STW5-2813 | MIL-S-8802 | ECL-0171 | 24MAR93 | 15AUG93 |
| BOLT | 1U75756-10 | ECL-0020 | 23MAR93 | N/A |

*REMARKS: The o-ring expiration dates represent that of a lubricated o-ring and not the o-ring itself.

8.0 LSS ENGINEERING AS-BUILT CONFIGURATION DATA (cont.)

RSRM: 033 BIO: 60 STS: 58

8.10 Exit Cone Installation (LH/RH) (continued)

LH: Second mate

| <u>ITEM</u> | <u>PART NO.</u> | <u>SERIAL/LOT NO.</u> | <u>DATE</u> | <u>EXP DATE</u> |
|--------------|-----------------|-----------------------|-------------|-----------------|
| EXIT CONE | 1U76970-01 | 0000017 | 25/FEB93 | N/A |
| GREASE | 1U51916-09 | ECL-0072 | 24FEB93 | 20AUG94 |
| O-RING, PRI | 1U75801-03 | 0000373 | *03MAR93 | 16MAR93 |
| O-RING, SEC | 1U75801-04 | 0000371 | *03MAR93 | 02AUG93 |
| Backfill RTV | STW5-2813 | ECL-0166 | 04MAR93 | 04MAR93 |
| BOLT | 1U75756-10 | ECL-0019 | 25FEB93 | N/A |

8.0 LSS ENGINEERING AS-BUILT CONFIGURATION DATA (cont.)

RSRM: 033 BIO: 60 STS: 58

8.11 Exit Cone Leak Check (LH/RH)

LH DATE: 04 MAR 93

| | | | |
|------------|-------------------------|---------|---------------|
| PRIMARY TO | | ALLOWED | ACTUAL RATE |
| SECONDARY | 83 PSIG DECAY LEAK RATE | .029 | 0.001922 SCCS |
| CAVITY | 30 PSIG DECAY LEAK RATE | .0082 | 0.00053 SCCS |

P/S PRINTOUT PLACED IN DATA BOOK BY: B. Hillard

270 DEGREE LEAK CHECK PORT

| <u>ITEM</u> | <u>PART NO.</u> | <u>LOT NO.</u> |
|-------------|-----------------|----------------|
| PLUG | 1U50159-02 | ECL-0019 |
| O-RING | 1U50228-25 | ECL-0068 |
| GREASE | 1U51916-09 | ECL-0072 |

270 DEGREE PLUG INSTALLATION VERIFIED BY: Bob Hillard

=====

RH DATE: 24 MAR 93

| | | | |
|------------|-------------------------|---------|---------------|
| PRIMARY TO | | ALLOWED | ACTUAL RATE |
| SECONDARY | 83 PSIG DECAY LEAK RATE | .029 | 0.002025 SCCS |
| CAVITY | 30 PSIG DECAY LEAK RATE | .0082 | 0.000381 SCCS |

P/S PRINTOUT PLACED IN DATA BOOK BY: T. White

270 DEGREE LEAK CHECK PORT

| <u>ITEM</u> | <u>PART NO.</u> | <u>LOT NO.</u> |
|-------------|-----------------|----------------|
| PLUG | 1U50159-02 | ECL-0019 |
| O-RING | 1U50228-25 | ECL-0068 |
| GREASE | 1U51916-09 | ECL-0075 |

270 DEGREE PLUG INSTALLATION VERIFIED BY: T. White

8.0 LSS ENGINEERING AS-BUILT CONFIGURATION DATA (cont.)

RSRM: 033 BIO: 60 STS: 58

8.12 LH Field Joint Mate

LH AFT FIELD JOINT MATE

AFT BOOSTER CLEVIS DATA

| <u>ITEM</u> | <u>PART NO.</u> | <u>SERIAL/LOT NO.</u> | <u>EXP DATE</u> | <u>DATE/TIME</u> |
|-------------|-----------------|-----------------------|-----------------|------------------|
| GREASE | 1U51916-09 | ECL-0075 | 10 MAR 95 | 12 MAY 93,04:30 |
| O-RING, PRI | 1U75801-01 | **0001248 | *08 JAN 93 | 12 MAT 93,09:46 |
| O-RING, SEC | 1U75801-01 | 0001239 | *14 JUL 93 | 12 MAY 93,17:00 |
| J-SEAL ADH. | STW5-3479 | ECL-0040 | 02 SEP 93 | 12 MAY 93,11:25 |

**REMARKS: PR-SB-BI060L-0001 Contamination found on primary o-ring at approx. 120 degrees and replaced. (J-seal adhesive STW5-3479. Contaminated o-ring serial number 0001224)

AFT CENTER TANG DATA

| <u>ITEM</u> | <u>PART NO.</u> | <u>SERIAL/LOT NO.</u> | <u>EXP DATE</u> | <u>DATE/TIME</u> |
|-------------|-----------------|-----------------------|-----------------|------------------|
| GREASE | 1U51916-09 | ECL-0075 | 10 MAR 95 | 12 MAY 93,05:30 |
| V-2 FILLER | STW3-3353 | ECL-0019 | N/A | 12 MAY 93,07:20 |
| O-RING, CAP | 1U75801-02 | 0000522 | *03 AUG 93 | 12 MAY 93,08:00 |
| J-SEAL ADH. | STW5-3479 | ECL-0040 | 02 SEP 93 | 12 MAY 93,09:15 |

* REMARKS: The o-ring expiration dates represent that of a lubricated o-ring and not the o-ring itself.

8.0 LSS ENGINEERING AS-BUILT CONFIGURATION DATA (cont.)

RSRM: 033 BIO: 60 STS: 58

8.12 LH Field Joint Mate (continued)

LH AFT FIELD JOINT MATE (continued)

| <u>ITEM</u> | <u>PART NO.</u> | <u>LOT NUMBER</u> | <u>QTY</u> |
|-------------|-----------------|-------------------|------------|
| PINS | 1U51055-12 | ECL-0016 | 36 |
| | | ECL-0001 | 59 |
| | | ECL-0008 | 8 |
| | | ECL-0007 | 2 |
| | | ECL-0004 | 55 |
| | | ECL-0002 | 17 |

| | <u>DATE</u> | <u>TIME</u> | <u>DEGREE LOCATION</u> |
|------------|-------------|-------------|------------------------|
| FIRST PIN: | 12 MAY 93 | 22:46 | 184 |
| LAST PIN: | 12 MAY 93 | 23:00 | 298 |

| <u>ITEM</u> | <u>PART NO.</u> | <u>LOT NUMBER</u> | <u>QTY</u> |
|--------------|-----------------|-------------------|------------|
| PIN RETAINER | 1U51899-12 | ECL-0030 | 177 |

DASH NO. OF WEDGE USED (IF ANY): N/A

DEGREE LOCATIONS USED AT: N/A

| <u>ITEM</u> | <u>PART NO.</u> | <u>SERIAL NO.</u> | <u>SERIAL NO.</u> | <u>SERIAL NO.</u> |
|-----------------------------|-----------------|-------------------|-------------------|-------------------|
| RETAINER BAND | 1U82840-02 | 0002024 | 0002015 | 0002027 |
| | 1U82840-03 | N/A | N/A | N/A |
| BAND JOINT LOCATIONS (DEG): | | 30-150 | 150-270 | 270-30 |

NOTE: Retainer Bands (1U82840-02 and 1U82840-03) are interchangeable. Only one retainer band is required at each designated location.

8.0 LSS ENGINEERING AS-BUILT CONFIGURATION DATA (cont.)

RSRM: 033 BIO: 60 STS: 58

8.12 LH Field Joint Mate (continued)

LH CENTER FIELD JOINT MATE

AFT CENTER CLEVIS DATA

| <u>ITEM</u> | <u>PART NO.</u> | <u>SERIAL/LOT NO.</u> | <u>EXP DATE</u> | <u>DATE/TIME</u> |
|-------------|-----------------|-----------------------|-----------------|------------------|
| GREASE | 1U51916-09 | ECL-0072 | 20 AUG 93 | 14 MAY 93,04:00 |
| O-RING, PRI | 1U75801-01 | 0001231 | *04 JUN 93 | 14 MAY 93,12:20 |
| O-RING, SEC | 1U75801-01 | 0001234 | *07 JUN 93 | 14 MAY 93,12:10 |
| J-SEAL ADH. | STW5-3479 | ECL-0040 | 02 SEP 93 | 14 MAY 93,14:00 |

FORWARD CENTER TANG DATA

| <u>ITEM</u> | <u>PART NO.</u> | <u>SERIAL/LOT NO.</u> | <u>EXP DATE</u> | <u>DATE/TIME</u> |
|-------------|-----------------|-----------------------|-----------------|------------------|
| GREASE | 1U51916-09 | ECL-0072 | 20 MAY 93 | 14 MAY 93,09:18 |
| V-2 FILLER | STW3-3353 | ECL-0020 | N/A | 14 MAY 93,09:40 |
| O-RING, CAP | 1U75801-02 | 0000526 | *18 SEP 93 | 14 MAY 93,09:55 |
| J-SEAL ADH. | STW5-3479 | ECL-0040 | 02 SEP 93 | 14 MAY 93,11:40 |

*REMARKS: The o-ring expiration dates represent that of a lubricated o-ring and not the o-ring itself.

8.0 LSS ENGINEERING AS-BUILT CONFIGURATION DATA (cont.)

RSRM: 033 BIO: 60 STS: 58

8.12 LH Field Joint Mate (continued)

LH CENTER FIELD JOINT MATE (continued)

| <u>ITEM</u> | <u>PART NO.</u> | <u>LOT NUMBER</u> | <u>QTY</u> |
|-------------|-----------------|-------------------|------------|
| PINS | 1U51055-12 | ECL-0001 | 61 |
| | | ECL-0002 | 23 |
| | | ECL-0003 | 2 |
| | | ECL-0004 | 17 |
| | | ECL-0005 | 25 |
| | | ECL-0007 | 32 |
| | | ECL-0009 | 11 |
| | | ECL-0011 | 6 |

| | <u>DATE</u> | <u>TIME</u> | <u>DEGREE LOCATION</u> |
|------------|-------------|-------------|------------------------|
| FIRST PIN: | 14 MAY 93 | 18:47 | 270 |
| LAST PIN: | 14 MAY 93 | 19:02 | 28 |

| <u>ITEM</u> | <u>PART NO.</u> | <u>LOT NUMBER</u> | <u>QTY</u> |
|--------------|-----------------|-------------------|------------|
| PIN RETAINER | 1U51899-12 | ECL-0034 | 177 |

DASH NO. OF WEDGE USED (IF ANY): N/A

DEGREE LOCATIONS USED AT: N/A

| <u>ITEM</u> | <u>PART NO.</u> | <u>SERIAL NO.</u> | <u>SERIAL NO.</u> | <u>SERIAL NO.</u> |
|-----------------------------|-----------------|-------------------|-------------------|-------------------|
| RETAINER BAND | 1U82840-02 | 0002034 | 0002026 | 0002017 |
| | 1U82840-03 | N/A | N/A | N/A |
| BAND JOINT LOCATIONS (DEG): | | 30-150 | 150-270 | 270-30 |

NOTE: Retainer Bands (1U82840-02 and 1U82840-03) are interchangeable. Only one retainer band is required at each designated location.

8.0 LSS ENGINEERING AS-BUILT CONFIGURATION DATA (cont.)

RSRM: 033 BIO: 60 STS: 58

8.12 LH Field Joint Mate (continued)

LH FORWARD FIELD JOINT MATE

FORWARD CENTER CLEVIS DATA

| <u>ITEM</u> | <u>PART NO.</u> | <u>SERIAL/LOT NO.</u> | <u>EXP DATE</u> | <u>DATE/TIME</u> |
|-------------|-----------------|-----------------------|-----------------|------------------|
| GREASE | 1U51916-09 | ECL-0075 | 10 MAR 95 | 16 MAY 93,02:40 |
| O-RING, PRI | 1U75801-01 | 0001236 | *07 JUN 93 | 16 MAY 93,06:42 |
| O-RING, SEC | 1U75801-01 | 0001235 | *07 JUN 93 | 16 MAY 93,06:30 |
| J-SEAL ADH. | STW5-3479 | ECL-0040 | 02 SEP 93 | 16 MAY 93,08:40 |

FORWARD TANG DATA

| <u>ITEM</u> | <u>PART NO.</u> | <u>SERIAL/LOT NO.</u> | <u>EXP DATE</u> | <u>DATE/TIME</u> |
|-------------|-----------------|-----------------------|-----------------|------------------|
| GREASE | 1U51916-09 | ECL-0075 | 10 MAR 95 | 16 MAY 93,04:20 |
| V-2 FILLER | STW3-3353 | ECL-0020 | N/A | 16 MAY 93,04:40 |
| O-RING, CAP | 1U75801-02 | 0000527 | *18 SEP 93 | 16 MAT 93,04:55 |
| J-SEAL ADH. | STW5-3479 | ECL-0040 | 02 SEP 93 | 16 MAY 93,06:10 |

*REMARKS: The o-ring expiration dates represent that of the lubricated o-ring (grease) and not the o-ring itself.

8.0 LSS ENGINEERING AS-BUILT CONFIGURATION DATA (cont.)

RSRM: 033 BIO: 60 STS: 58

8.12 LH Field Joint Mate (continued)

LH FORWARD FIELD JOINT MATE (continued)

| <u>ITEM</u> | <u>PART NO.</u> | <u>LOT NUMBER</u> | <u>QTY</u> |
|-------------|-----------------|-------------------|------------|
| PINS | 1U51055-12 | ECL-0003 | 3 |
| | | ECL-0026 | 174 |

| | <u>DATE</u> | <u>TIME</u> | <u>DEGREE LOCATION</u> |
|------------|-------------|-------------|------------------------|
| FIRST PIN: | 16 MAY 93 | 16:00 | 104 |
| LAST PIN: | 16 MAY 93 | 16:13 | 350 |

| <u>ITEM</u> | <u>PART NO.</u> | <u>LOT NUMBER</u> | <u>QTY</u> |
|--------------|-----------------|-------------------|------------|
| PIN RETAINER | 1U51899-12 | ECL-0034 | 102 |
| | | ECL-0025 | 75 |

DASH NO. OF WEDGE USED (IF ANY): N/A

DEGREE LOCATIONS USED AT: N/A

| <u>ITEM</u> | <u>PART NO.</u> | <u>SERIAL NO.</u> | <u>SERIAL NO.</u> | <u>SERIAL NO.</u> |
|-----------------------------|-----------------|-------------------|-------------------|-------------------|
| RETAINER BAND | 1U82840-02 | 0002035 | 0002020 | 0002033 |
| | 1U82840-03 | N/A | N/A | N/A |
| BAND JOINT LOCATIONS (DEG): | | 30-150 | 150-270 | 270-30 |


NOTE: Retainer Bands (1U82840-02 and 1U82840-03) are interchangeable. Only one retainer band is required at each designated location.

8.0 LSS ENGINEERING AS-BUILT CONFIGURATION DATA (cont.)

8.13 LSS Data

| DIFF IN DELTAS FROM CIRCULAR | ANGLE DIFF | RSRM: 033 | BIO: 60 | STS: 58 |
|------------------------------|------------|-----------|---------|---------|
| 0 | -0.037 | 320 | 0.003 | |
| 10 | -0.015 | 330 | 0.013 | |
| 20 | 0.016 | 340 | 0.007 | |
| 30 | 0.039 | 350 | 0.036 | |
| 40 | 0.031 | | | |
| 50 | -0.010 | | | |
| 60 | -0.049 | | | |
| 70 | -0.051 | | | |
| 80 | -0.029 | | | |
| 90 | -0.014 | | | |
| 100 | -0.011 | | | |
| 110 | 0.003 | | | |
| 120 | 0.034 | | | |
| 130 | 0.069 | | | |
| 140 | 0.094 | | | |
| 150 | 0.094 | | | |
| 160 | 0.060 | | | |
| 170 | 0.004 | | | |
| 180 | -0.054 | | | |
| 190 | -0.083 | | | |
| 200 | -0.082 | | | |
| 210 | -0.081 | | | |
| 220 | -0.077 | | | |
| 230 | -0.040 | | | |
| 240 | 0.005 | | | |
| 250 | 0.025 | | | |
| 260 | 0.035 | | | |
| 270 | 0.053 | | | |
| 280 | 0.052 | | | |
| 290 | 0.032 | | | |
| 300 | 0.013 | | | |
| 310 | -0.001 | | | |

LAC TANG VS. LAB CLEVIS BI060 VAB X-FER AISLE 5-11-93
0-180=70.55K 90-270=232.9K 1300HRS
* Delta difference greater than 0.125




8.0 LSS ENGINEERING AS-BUILT CONFIGURATION DATA (cont.)

RSRM: 033 BIO: 60 STS: 58

8.13 LH Sine Bar Data (continued)

| DIFF IN DELTAS FROM CIRC | |
|--------------------------|------------|
| ANGLE DIFF | ANGLE DIFF |
| 0 | 0.003 |
| 10 | 0.000 |
| 20 | 0.006 |
| 30 | 0.019 |
| 40 | 0.028 |
| 50 | 0.031 |
| 60 | 0.027 |
| 70 | 0.015 |
| 80 | 0.009 |
| 90 | 0.020 |
| 100 | 0.033 |
| 110 | 0.021 |
| 120 | -0.022 |
| 130 | -0.065 |
| 140 | -0.075 |
| 150 | -0.051 |
| 160 | -0.020 |
| 170 | 0.003 |
| 180 | 0.025 |
| 190 | 0.047 |
| 200 | 0.047 |
| 210 | 0.026 |
| 220 | 0.015 |
| 230 | 0.017 |
| 240 | 0.024 |
| 250 | 0.030 |
| 260 | 0.029 |
| 270 | 0.019 |
| 280 | -0.003 |
| 290 | -0.033 |
| 300 | -0.058 |
| 310 | -0.068 |

LFC TANG 61060 VS LAC CLEV13 61060 VAB XFER AISLE 5/13/93
0-180-148K 90-270-152K
* Delta difference greater than 0.125



REVISION

DOC NO. TWR-64563 VOL
SEC PAGE


8.0 LSS ENGINEERING AS-BUILT CONFIGURATION DATA (cont.)

RSRM: 033 BIO: 60 STS: 58

8.13 LH Sine Bar Data (continued)

| DIFF IN DELTAS FROM CIRC | | ANGLE DIFF | |
|--------------------------|------------|------------|------------|
| ANGLE DIFF | ANGLE DIFF | ANGLE DIFF | ANGLE DIFF |
| 0 | 0.019 | 320 | -0.042 |
| 10 | 0.017 | 330 | -0.022 |
| 20 | 0.023 | 340 | 0.003 |
| 30 | 0.040 | 350 | 0.017 |
| 40 | 0.052 | | |
| 50 | 0.041 | | |
| 60 | 0.009 | | |
| 70 | -0.023 | | |
| 80 | -0.037 | | |
| 90 | -0.038 | | |
| 100 | -0.038 | | |
| 110 | -0.038 | | |
| 120 | -0.033 | | |
| 130 | -0.027 | | |
| 140 | -0.013 | | |
| 150 | 0.019 | | |
| 160 | 0.050 | | |
| 170 | 0.053 | | |
| 180 | 0.033 | | |
| 190 | 0.011 | | |
| 200 | -0.005 | | |
| 210 | -0.015 | | |
| 220 | -0.016 | | |
| 230 | 0.001 | | |
| 240 | 0.023 | | |
| 250 | 0.031 | | |
| 260 | 0.021 | | |
| 270 | 0.005 | | |
| 280 | -0.009 | | |
| 290 | -0.024 | | |
| 300 | -0.039 | | |
| 310 | -0.048 | | |

LF T VS LFC CLEVIS BIO60 VAB X=FER AISLE .5/93
0-18. 58.3K; 90-270-173.65K 0725HRS



REVISION _____

DOC NO TWR-64563
SEC _____

PAGE _____
VOL _____

8.0 LSS ENGINEERING AS-BUILT CONFIGURATION DATA (cont.)

RSRM: 033 BIO: 60 STS: 58

8.14 RH Field Joint Mate

RH AFT FIELD JOINT MATE

AFT BOOSTER CLEVIS DATA

| <u>ITEM</u> | <u>PART NO.</u> | <u>SERIAL/LOT NO.</u> | <u>EXP DATE</u> | <u>DATE/TIME</u> |
|-------------|-----------------|-----------------------|-----------------|------------------|
| GREASE | 1U51916-09 | ECL-0075 | 10MAR95 | 19MAY93,12:30 |
| O-RING, PRI | 1U75801-01 | 0001240 | *08JUN93 | 19MAY93,17:40 |
| O-RING, SEC | 1U75801-01 | 0001238 | *08JUN93 | 19MAY93,17:20 |
| J-SEAL ADH. | STW5-3479 | ECL-0040 | 02SEP93 | 19MAY93,18:30 |

AFT CENTER TANG DATA

| <u>ITEM</u> | <u>PART NO.</u> | <u>SERIAL/LOT NO.</u> | <u>EXP DATE</u> | <u>DATE/TIME</u> |
|-------------|-----------------|-----------------------|-----------------|------------------|
| GREASE | 1U51916-09 | ECL-0075 | 10MAR95 | 19MAY93,14:10 |
| V-2 FILLER | STW3-3353 | ECL-0020 | N/A | 19MAY93,15:00 |
| O-RING, CAP | 1U75801-02 | 0000530 | *18SEP93 | 19MAY93,16:30 |
| J-SEAL ADH. | STW5-3479 | ECL-0040 | 02SEP93 | 19MAY93,17:00 |

*REMARKS: The o-ring expiration dates represent that of a lubricated o-ring and not the o-ring itself.

8.0 LSS ENGINEERING AS-BUILT CONFIGURATION DATA (cont.)

RSRM: 033 BIO: 60 STS: 58

8.14 RH Field Joint Mate (continued)

RH AFT FIELD JOINT MATE (continued)

| <u>ITEM</u> | <u>PART NO.</u> | <u>LOT NUMBER</u> | <u>QTY</u> |
|-------------|-----------------|-------------------|------------|
| PINS | 1U51055-12 | ECL-0019 | 56 |
| | | ECL-0015 | 1 |
| | | ECL-0010 | 38 |
| | | ECL-0006 | 3 |
| | | ECL-0009 | 20 |
| | | ECL-0007 | 53 |
| | | ECL-0002 | 2 |

| | <u>DATE</u> | <u>TIME</u> | <u>DEGREE LOCATION</u> |
|------------|-------------|-------------|------------------------|
| FIRST PIN: | 20 MAY 93 | 23:50 | 180 |
| LAST PIN: | 20 MAY 93 | 23:59 | 290 |

| <u>ITEM</u> | <u>PART NO.</u> | <u>LOT NUMBER</u> | <u>QTY</u> |
|--------------|-----------------|-------------------|------------|
| PIN RETAINER | 1U51899-13 | ECL-0019 | 177 |

DASH NO. OF WEDGE USED (IF ANY): N/A

DEGREE LOCATIONS USED AT: N/A

| <u>ITEM</u> | <u>PART NO.</u> | <u>SERIAL NO.</u> | <u>SERIAL NO.</u> | <u>SERIAL NO.</u> |
|-----------------------------|-----------------|-------------------|-------------------|-------------------|
| RETAINER BAND | 1U82840-02 | 0002022 | 0002038 | 0002029 |
| | 1U82840-03 | N/A | N/A | N/A |
| BAND JOINT LOCATIONS (DEG): | | 30-150 | 150-270 | 270-30 |

NOTE: Retainer Bands (1U82840-02 and 1U82840-03) are interchangeable. Only one retainer band is required at each designated location.

8.0 LSS ENGINEERING AS-BUILT CONFIGURATION DATA (cont.)

RSRM: 033 BIO: 60 STS: 58

8.14 RH Field Joint Mate (continued)

RH CENTER FIELD JOINT MATE

AFT CENTER CLEVIS DATA

| <u>ITEM</u> | <u>PART NO.</u> | <u>SERIAL/LOT NO.</u> | <u>EXP DATE</u> | <u>DATE/TIME</u> |
|-------------|-----------------|-----------------------|-----------------|------------------|
| GREASE | 1U51916-09 | ECL-0075 | 10MAR95 | 21MAY93,21:30 |
| O-RING, PRI | 1U75801-01 | 0001249 | *14JUL93 | 21MAY93,22:35 |
| O-RING, SEC | 1U75801-01 | 0001237 | *08JUN93 | 21MAY93,22:15 |
| J-SEAL ADH. | STW5-3479 | ECL-0040 | 02SEP93 | 22MAY93,23:45 |

FORWARD CENTER TANG DATA

| <u>ITEM</u> | <u>PART NO.</u> | <u>SERIAL/LOT NO.</u> | <u>EXP DATE</u> | <u>DATE/TIME</u> |
|-------------|-----------------|-----------------------|-----------------|------------------|
| GREASE | 1U51916-09 | ECL-0075 | 10MAR95 | 21MAY93,13:30 |
| V-2 FILLER | STW3-3353 | ECL-0018 | N/A | 21MAY93,14:25 |
| O-RING, CAP | 1U75801-02 | 0000529 | *18SEP93 | 21MAY93,14:35 |
| J-SEAL ADH. | STW5-3479 | ECL-0040 | 02SEP93 | 21MAY93,15:15 |

*REMARKS: The o-ring expiration dates represent that of the lubricated o-ring (grease) and not the o-ring itself.

8.0 LSS ENGINEERING AS-BUILT CONFIGURATION DATA (cont.)

RSRM: 033 BIO: 60 STS: 58

8.14 RH Field Joint Mate (continued)

RH CENTER FIELD JOINT MATE (continued)

| <u>ITEM</u> | <u>PART NO.</u> | <u>LOT NUMBER</u> | <u>QTY</u> |
|-------------|-----------------|-------------------|------------|
| PINS | 1U51055-12 | ECL-0029 | 177 |

| | <u>DATE</u> | <u>TIME</u> | <u>DEGREE LOCATION</u> |
|------------|-------------|-------------|------------------------|
| FIRST PIN: | 22 MAY 93 | 04:45 | 270 |
| LAST PIN: | 22 MAY 93 | 04:50 | 342 |

| <u>ITEM</u> | <u>PART NO.</u> | <u>LOT NUMBER</u> | <u>QTY</u> |
|--------------|-----------------|-------------------|------------|
| PIN RETAINER | 1U51899-13 | ECL-0019 | 177 |

DASH NO. OF WEDGE USED (IF ANY): N/A

DEGREE LOCATIONS USED AT: N/A

| <u>ITEM</u> | <u>PART NO.</u> | <u>SERIAL NO.</u> | <u>SERIAL NO.</u> | <u>SERIAL NO.</u> |
|-----------------------------|-----------------|-------------------|-------------------|-------------------|
| RETAINER BAND | 1U82840-02 | 0000343 | 0000344 | 0000361 |
| | 1U82840-03 | N/A | N/A | N/A |
| BAND JOINT LOCATIONS (DEG): | | 30-150 | 150-270 | 270-30 |

NOTE: Retainer Bands (1U82840-02 and 1U82840-03) are interchangeable. Only one retainer band is required at each designated location.

8.0 LSS ENGINEERING AS-BUILT CONFIGURATION DATA (cont.)

RSRM: 033 BIO: 60 STS: 58

8.14 RH Field Joint Mate (continued)

RH FORWARD FIELD JOINT MATE

FORWARD CENTER CLEVIS DATA

| <u>ITEM</u> | <u>PART NO.</u> | <u>SERIAL/LOT NO.</u> | <u>EXP DATE</u> | <u>DATE/TIME</u> |
|-------------|-----------------|-----------------------|-----------------|------------------|
| GREASE | 1U51916-09 | ECL-0075 | 10MAR95 | 25MAY93,03:15 |
| O-RING, PRI | 1U75801-01 | 0001246 | *13JUL93 | 25MAY93,10:15 |
| O-RING, SEC | 1U75801-01 | 0001247 | *13JUL93 | 25MAY93,10:00 |
| J-SEAL ADH. | STW5-3479 | ECL-0040 | 02SEP93 | 25MAY93,11:10 |

FORWARD TANG DATA

| <u>ITEM</u> | <u>PART NO.</u> | <u>SERIAL/LOT NO.</u> | <u>EXP DATE</u> | <u>DATE/TIME</u> |
|-------------|-----------------|-----------------------|-----------------|------------------|
| GREASE | 1U51916-09 | ECL-0075 | 10MAR95 | 25MAY93,04:30 |
| V-2 FILLER | STW3-3353 | ECL-0020 | N/A | 25MAY93,05:10 |
| O-RING, CAP | 1U75801-02 | 0000525 | *08SEP93 | 25MAY93,05:25 |
| J-SEAL ADH. | STW5-3479 | ECL-0040 | 02SEP93 | 25MAY93,06:52 |

*REMARKS: The o-ring expiration dates represent that of a lubricated o-ring and not the o-ring itself.

8.0 LSS ENGINEERING AS-BUILT CONFIGURATION DATA (cont.)

RSRM: 033 BIO: 60 STS: 58

8.14 RH Field Joint Mate (continued)

RH FORWARD FIELD JOINT MATE (continued)

| <u>ITEM</u> | <u>PART NO.</u> | <u>LOT NUMBER</u> | <u>QTY</u> |
|-------------|-----------------|-------------------|------------|
| PINS | 1U51055-12 | ECL-0029 | 177 |

| | <u>DATE</u> | <u>TIME</u> | <u>DEGREE LOCATION</u> |
|------------|-------------|-------------|------------------------|
| FIRST PIN: | 25 MAY 93 | 16:02 | 82 |
| LAST PIN: | 25 MAY 93 | 16:11 | 166 |

| <u>ITEM</u> | <u>PART NO.</u> | <u>LOT NUMBER</u> | <u>QTY</u> |
|--------------|-----------------|-------------------|------------|
| PIN RETAINER | 1U51899-12 | ECL-0034 | 121 |
| | | ECL-0011 | 50 |
| | | ECL-0030 | 6 |

DASH NO. OF WEDGE USED (IF ANY): N/A

DEGREE LOCATIONS USED AT: N/A

| <u>ITEM</u> | <u>PART NO.</u> | <u>SERIAL NO.</u> | <u>SERIAL NO.</u> | <u>SERIAL NO.</u> |
|-----------------------------|-----------------|-------------------|-------------------|-------------------|
| RETAINER BAND | 1U82840-02 | 0002032 | 0002023 | 0002018 |
| | 1U82840-03 | N/A | N/A | N/A |
| BAND JOINT LOCATIONS (DEG): | | 30-150 | 150-270 | 270-30 |

NOTE: Retainer Bands (1U82840-02 and 1U82840-03) are interchangeable. Only one retainer band is required at each designated location.


8.0 LSS ENGINEERING AS-BUILT CONFIGURATION DATA (cont.)

RSRM: 033 BIO: 60 STS: 58

8.15 RH S. Bar Data

| DIFF IN DELTAS FROM CIRC | ANGLE DIFF | ANGLE DIFF |
|--------------------------|------------|------------|
| 0 | -0.035 | 320 -0.057 |
| 10 | 0.006 | 330 -0.052 |
| 20 | 0.052 | 340 -0.052 |
| 30 | 0.073 | 350 -0.053 |
| 40 | 0.060 | |
| 50 | 0.030 | |
| 60 | 0.006 | |
| 70 | -0.001 | |
| 80 | 0.000 | |
| 90 | -0.005 | |
| 100 | -0.012 | |
| 110 | -0.015 | |
| 120 | -0.008 | |
| 130 | 0.012 | |
| 140 | 0.033 | |
| 150 | 0.033 | |
| 160 | 0.006 | |
| 170 | -0.030 | |
| 180 | -0.057 | |
| 190 | -0.064 | |
| 200 | -0.050 | |
| 210 | -0.022 | |
| 220 | 0.007 | |
| 230 | 0.034 | |
| 240 | 0.060 | |
| 250 | 0.074 | |
| 260 | 0.075 | |
| 270 | 0.058 | |
| 280 | 0.020 | |
| 290 | -0.021 | |
| 300 | -0.047 | |
| 310 | -0.058 | |

RAC TANG BIO-60R V.S RAB CLEVIS BIO-60R VAB X-AISLE 5-18-93
0-180=67K ; 90-270=238K 1800 HRS. Q.A. JACKSON
* Delta difference greater than 0.125




8.0 LSS ENGINEERING AS-BUILT CONFIGURATION DATA (cont.)

RSRM: 033 BIO: 60 STS: 58

8.15 RH Sine Bar Data (continued)

| DIFF IN DELTAS FROM CIRC | |
|--------------------------|------------|
| ANGLE DIFF | ANGLE DIFF |
| 0 -0.091 | 320 0.030 |
| 10 -0.075 | 330 0.016 |
| 20 -0.031 | 340 -0.032 |
| 30 0.034 | 350 -0.077 |
| 40 0.075 | |
| 50 0.065 | |
| 60 0.039 | |
| 70 0.042 | |
| 80 0.072 | |
| 90 0.078 | |
| 100 0.030 | |
| 110 -0.033 | |
| 120 -0.071 | |
| 130 -0.079 | |
| 140 -0.063 | |
| 150 -0.039 | |
| 160 -0.031 | |
| 170 -0.032 | |
| 180 -0.010 | |
| 190 0.026 | |
| 200 0.049 | |
| 210 0.057 | |
| 220 0.046 | |
| 230 0.012 | |
| 240 -0.022 | |
| 250 -0.035 | |
| 260 -0.015 | |
| 270 0.016 | |
| 280 0.022 | |
| 290 0.011 | |
| 300 0.001 | |
| 310 0.013 | |

RFC TANG VS RAC CLEVIS BIO60 VAB X-FER AISLE, 5-20-93
0-180-99.9K, 90-270-203.7K, 2050 HRS., Clocked +30 DEG.
* Delta difference greater than 0.125



REVISION

DOC NO TWR-64563 VOL
SEC PAGE


8.0 LSS ENGINEERING AS-BUILT CONFIGURATION DATA (cont.)

RSRM: 033 BIO: 60 STS: 58

8.15 R Data (continued)

| DIFF IN DELTAS FROM CIRCULAR | ANGLE DIFF | ANGLE DIFF |
|------------------------------|------------|------------|
| 0 | -0.030 | 320 -0.048 |
| 10 | -0.050 | 330 -0.028 |
| 20 | -0.044 | 340 -0.023 |
| 30 | -0.002 | 350 -0.019 |
| 40 | 0.038 | |
| 50 | 0.044 | |
| 60 | 0.036 | |
| 70 | 0.027 | |
| 80 | 0.022 | |
| 90 | 0.031 | |
| 100 | 0.042 | |
| 110 | 0.041 | |
| 120 | 0.024 | |
| 130 | -0.011 | |
| 140 | -0.046 | |
| 150 | -0.060 | |
| 160 | -0.061 | |
| 170 | -0.058 | |
| 180 | -0.041 | |
| 190 | -0.017 | |
| 200 | 0.000 | |
| 210 | 0.018 | |
| 220 | 0.031 | |
| 230 | 0.036 | |
| 240 | 0.038 | |
| 250 | 0.032 | |
| 260 | 0.026 | |
| 270 | 0.038 | |
| 280 | 0.053 | |
| 290 | 0.033 | |
| 300 | -0.021 | |
| 310 | -0.056 | |

RFS TANG BIO-60 VS RFC CLEVIS BIO-60 VAB X-FER AISLE 5-24-93
0-180-161K 90-270-174K 1159
* Delta difference greater than 0.125



8.0 LSS ENGINEERING AS-BUILT CONFIGURATION DATA (cont.)

RSRM: 033 BIO: 60 STS: 58

8.16 LH Joint Leak Checks & 45 Deg Plug

LH AFT FIELD JOINT

DATE: 13 MAY 93

| PRIMARY TO SECONDARY CAVITY | | ALLOWED | ACTUAL RATE | |
|-----------------------------------|---------------------------|---------|-------------|------|
| | 1000 PSIG DECAY LEAK RATE | .10 | 0.0210 | SCCS |
| | 30 PSIG DECAY LEAK RATE | .0082 | 0.0004 | SCCS |

DATE: 13 MAY 93

| PRIMARY TO BARRIER CAVITY | 100 PSIG | | ALLOWED | ACTUAL RATE | |
|---------------------------------|----------|-----------------|---------|-------------|------|
| | | DECAY LEAK RATE | .037 | 0.0225 | SCCS |
| | 30 PSIG | PRESS RISE RATE | .037 | 0.0005 | SCCS |
| | | DECAY LEAK RATE | .0082 | -0.0005 | SCCS |
| | | PRESS RISE RATE | .0082 | 0.0004 | SCCS |

45 DEGREE LEAK CHECK PORT

| <u>ITEM</u> | <u>PART NO.</u> | <u>LOT NO.</u> |
|-------------|-----------------|----------------|
| PLUG | 1U100269-03 | ECL-0024 |
| O-RING | 1U50228-15 | ECL-0121 |
| GREASE | 1U51916-09 | ECL-0072 |

REVISION _____

8.0 LSS ENGINEERING AS-BUILT CONFIGURATION DATA (cont.)

RSRM: 033 BIO: 60 STS: 58

8.16 LH Joint Leak Checks & 45 Deg Plug (continued)

LH CENTER FIELD JOINT

DATE: 16 MAY 93

| PRIMARY TO | | ALLOWED | ACTUAL RATE |
|------------|---------------------------|---------|-------------|
| SECONDARY | 1000 PSIG DECAY LEAK RATE | .10 | 0.0146 SCCS |
| CAVITY | 30 PSIG DECAY LEAK RATE | .0082 | 0.0004 SCCS |

DATE: 17 MAY 93

| | | | ALLOWED | ACTUAL RATE |
|---------------------------------|----------|-----------------|---------|-------------|
| PRIMARY TO BARRIER CAVITY | 100 PSIG | DECAY LEAK RATE | .037 | 0.0112 SCCS |
| | | PRESS RISE RATE | .037 | 0.0002 SCCS |
| | 30 PSIG | DECAY LEAK RATE | .0082 | 0.0010 SCCS |
| | | PRESS RISE RATE | .0082 | 0.0002 SCCS |

45 DEGREE LEAK CHECK PORT

| <u>ITEM</u> | <u>PART NO.</u> | <u>LOT NO.</u> |
|-------------|-----------------|----------------|
| PLUG | 1U100269-03 | ECL-0024 |
| O-RING | 1U50228-15 | ECL-0121 |
| GREASE | 1U51916-09 | ECL-0072 |

8.0 LSS ENGINEERING AS-BUILT CONFIGURATION DATA (cont.)

RSRM: 033 BIO: 60 STS: 58

8.16 LH Joint Leak Checks & 45 Deg Plug (continued)

LH FORWARD FIELD JOINT

DATE: 19 MAY 93

| PRIMARY TO | | ALLOWED | ACTUAL RATE | |
|------------|---------------------------|---------|-------------|------|
| SECONDARY | 1000 PSIG DECAY LEAK RATE | .10 | 0.0305 | SCCS |
| CAVITY | 30 PSIG DECAY LEAK RATE | .0082 | 0.0001 | SCCS |

DATE: 20 MAY 93

| | | | ALLOWED | ACTUAL RATE | |
|---------------------------------|----------|-----------------|---------|-------------|------|
| PRIMARY TO BARRIER CAVITY | 100 PSIG | DECAY LEAK RATE | .037 | 0.0101 | SCCS |
| | | PRESS RISE RATE | .037 | 0.0003 | SCCS |
| | 30 PSIG | DECAY LEAK RATE | .0082 | 0.0005 | SCCS |
| | | PRESS RISE RATE | .0082 | 0.0002 | SCCS |

45 DEGREE LEAK CHECK PORT

| <u>ITEM</u> | <u>PART NO.</u> | <u>LOT NO.</u> |
|-------------|-----------------|----------------|
| PLUG | 1U100269-03 | ECL-0024 |
| O-RING | 1U50228-15 | ECL-0015 |
| GREASE | 1U51916-09 | ECL-0072 |

REVISION _____

8.0 LSS ENGINEERING AS-BUILT CONFIGURATION DATA (cont.)

RSRM: 033 BIO: 60 STS: 58

8.17 RH Joint Leak Checks & 45 Deg Plug

RH APT FIELD JOINT

DATE: 20 MAY 93

| PRIMARY TO SECONDARY CAVITY | | ALLOWED | ACTUAL RATE | |
|-----------------------------------|---------------------------|---------|-------------|------|
| | 1000 PSIG DECAY LEAK RATE | .10 | 0.0149 | SCCS |
| | 30 PSIG DECAY LEAK RATE | .0082 | -0.0005 | SCCS |

DATE: 20 MAY 93

| PRIMARY TO BARRIER CAVITY | 100 PSIG | DECAY LEAK RATE | ALLOWED | ACTUAL RATE | |
|---------------------------------|----------|-----------------|---------|-------------|------|
| | | PRESS RISE RATE | .037 | 0.0200 | SCCS |
| | 30 PSIG | DECAY LEAK RATE | .037 | 0.0003 | SCCS |
| | | PRESS RISE RATE | .0082 | 0.0003 | SCCS |
| | 30 PSIG | DECAY LEAK RATE | .0082 | 0.0002 | SCCS |
| | | PRESS RISE RATE | .0082 | 0.0002 | SCCS |

45 DEGREE LEAK CHECK PORT

| <u>ITEM</u> | <u>PART NO.</u> | <u>LOT NO.</u> |
|-------------|-----------------|----------------|
| PLUG | 1U100269-03 | ECL-0024 |
| O-RING | 1U50228-15 | ECL-0121 |
| GREASE | 1U51916-09 | ECL-0072 |

REVISION _____

8.0 LSS ENGINEERING AS-BUILT CONFIGURATION DATA (cont.)

RSRM: 033 BIO: 60 STS: 58

8.17 RH Joint Leak Checks & 45 Deg Plug (continued)

RH CENTER FIELD JOINT

DATE: 24 MAY 93

| PRIMARY TO | | ALLOWED | ACTUAL RATE |
|------------|---------------------------|---------|--------------|
| SECONDARY | 1000 PSIG DECAY LEAK RATE | .10 | 0.0105 SCCS |
| CAVITY | 30 PSIG DECAY LEAK RATE | .0082 | -0.0002 SCCS |

DATE: 24 MAY 93

| | | | ALLOWED | ACTUAL RATE |
|---------------------------------|----------|-----------------|---------|-------------|
| PRIMARY TO BARRIER CAVITY | 100 PSIG | DECAY LEAK RATE | .037 | 0.0178 SCCS |
| | | PRESS RISE RATE | .037 | 0.0005 SCCS |
| | 30 PSIG | DECAY LEAK RATE | .0082 | 0.0005 SCCS |
| | | PRESS RISE RATE | .0082 | 0.0004 SCCS |

45 DEGREE LEAK CHECK PORT

| <u>ITEM</u> | <u>PART NO.</u> | <u>LOT NO.</u> |
|-------------|-----------------|----------------|
| PLUG | 1U100269-03 | ECL-0024 |
| O-RING | 1U50228-15 | ECL-0121 |
| GREASE | 1U51916-09 | ECL-0075 |

8.0 LSS ENGINEERING AS-BUILT CONFIGURATION DATA (cont.)

RSRM: 033 BIO: 60 STS: 58

8.17 RH Joint Leak Checks & 45 Deg Plug (continued)

RH FORWARD FIELD JOINT

DATE: 26 MAY 93

| PRIMARY TO | | ALLOWED | ACTUAL RATE | |
|------------|---------------------------|---------|-------------|------|
| SECONDARY | 1000 PSIG DECAY LEAK RATE | .10 | 0.0225 | SCCS |
| CAVITY | 30 PSIG DECAY LEAK RATE | .0082 | 0.00002 | SCCS |

DATE: 26 MAY 93

| | | | ALLOWED | ACTUAL RATE | |
|---------------------------------|----------|-----------------|---------|-------------|------|
| PRIMARY TO BARRIER CAVITY | 100 PSIG | DECAY LEAK RATE | .037 | 0.0068 | SCCS |
| | | PRESS RISE RATE | .037 | 0.0003 | SCCS |
| | 30 PSIG | DECAY LEAK RATE | .0082 | 0.0011 | SCCS |
| | | PRESS RISE RATE | .0082 | 0.0001 | SCCS |

45 DEGREE LEAK CHECK PORT

| <u>ITEM</u> | <u>PART NO.</u> | <u>LOT NO.</u> |
|-------------|-----------------|----------------|
| PLUG | 1U100269-03 | ECL-0024 |
| O-RING | 1U50228-15 | ECL-0121 |
| GREASE | 1U51916-09 | ECL-0072 |

8.0 LSS ENGINEERING AS-BUILT CONFIGURATION DATA (cont.)

RSRM: 033 BIO: 60 STS: 58

8.18 LH 135 Vent Plug & Leak Check

LH AFT FIELD JOINT 135 DEGREE VENT PORT PLUG LEAK CHECK

| <u>ITEM</u> | <u>PART NO.</u> | <u>SERIAL/LOT NO.</u> |
|-------------------|-----------------|-----------------------|
| GREASE | 1U51916-09 | ECL-0072 |
| PLUG, BOTTOM | 1U76425-01 | ECL-0014 |
| PLUG, TOP | 1U76425-03 | ECL-0028 |
| PLUG, CLOSURE | 1U50159-02 | ECL-0019 |
| O-RING, PRIMARY | 1U50228-44 | ECL-0015 |
| O-RING, SECONDARY | 1U50228-15 | ECL-0121 |
| O-RING, CLOSURE | 1U50228-25 | ECL-0068 |

LEAK TEST DATA

1. START TIME (TO THE SECOND): 22:36:00
2. INITIAL ISOLATION PRESSURE: 1003.000 PSIG
+ 14.696
1017.696 = P1
3. INITIAL ISOLATION TEMPERATURE: 77.4 DEGREES F
+ 459.7
537.1 = T1
4. STOP TIME (TO THE SECOND): 22:51:00 (MINUTES * 60)
(PLUS SECONDS)
ELAPSED TIME IN SECONDS: 900 = T
5. FINAL ISOLATION PRESSURE: 1000.000 PSIG
+ 14.696
1014.696 = P2
6. FINAL ISOLATION TEMPERATURE: 77.8 DEGREES F
+ 459.7
537.5 = T2

V = 1.4

CALCULATE THE LEAK RATE PER THE FOLLOWING:

$$\text{LEAK RATE} = \frac{579.478 (1.4)}{T} (P1/T1 - P2/T2)$$

LEAK RATE = 0.0063 SCCS

V = 1.4

8.0 LSS ENGINEERING AS-BUILT CONFIGURATION DATA (cont.)

RSRM: 033 BIO: 60 STS: 58

8.18 LH 135 Vent Plug & Leak Check (continued)

LH CENTER FIELD JOINT 135 DEGREE VENT PORT PLUG LEAK CHECK

| <u>ITEM</u> | <u>PART NO.</u> | <u>SERIAL/LOT NO.</u> |
|-------------------|-----------------|-----------------------|
| GREASE | 1U51916-09 | ECL-0072 |
| PLUG, BOTTOM | 1U76425-01 | ECL-0014 |
| PLUG, TOP | 1U76425-03 | ECL-0028 |
| PLUG, CLOSURE | 1U50159-02 | ECL-0019 |
| O-RING, PRIMARY | 1U50228-44 | ECL-0015 |
| O-RING, SECONDARY | 1U50228-15 | ECL-0121 |
| O-RING, CLOSURE | 1U50228-25 | ECL-0068 |

LEAK TEST DATA

1. START TIME (TO THE SECOND): 18:30:00
2. INITIAL ISOLATION PRESSURE: 994.000 PSIG
+ 14.696
1008.696 = P1
3. INITIAL ISOLATION TEMPERATURE: 78.2 DEGREES F
+ 459.7
537.9 = T1
4. STOP TIME (TO THE SECOND): 18:45:00 (MINUTES * 60)
ELAPSED TIME IN SECONDS: 900 = T (PLUS SECONDS)
5. FINAL ISOLATION PRESSURE: 990.000 PSIG
+ 14.696
1004.696 = P2
6. FINAL ISOLATION TEMPERATURE: 78.1 DEGREES F
+ 459.7
537.8 = T2

V = 1.4

CALCULATE THE LEAK RATE PER THE FOLLOWING:

$$\text{LEAK RATE} = \frac{579.478 (1.4)}{T} (P1/T1 - P2/T2)$$

LEAK RATE = 0.0064 SCCS

V = 1.4

8.0 LSS ENGINEERING AS-BUILT CONFIGURATION DATA (cont.)

RSRM: 033 BIO: 60 STS: 58

8.18 LH 135 Vent Plug & Leak Check (continued)

LH FORWARD FIELD JOINT 135 DEGREE VENT PORT PLUG LEAK CHECK

| <u>ITEM</u> | <u>PART NO.</u> | <u>SERIAL/LOT NO.</u> |
|-------------------|-----------------|-----------------------|
| GREASE | 1U51916-09 | ECL-0072 |
| PLUG, BOTTOM | 1U76425-01 | ECL-0014 |
| PLUG, TOP | 1U76425-03 | ECL-0021 |
| PLUG, CLOSURE | 1U50159-02 | ECL-0019 |
| O-RING, PRIMARY | 1U50228-44 | ECL-0015 |
| O-RING, SECONDARY | 1U50228-15 | ECL-0121 |
| O-RING, CLOSURE | 1U50228-25 | ECL-0068 |

LEAK TEST DATA

1. START TIME (TO THE SECOND): 04:55:00
2. INITIAL ISOLATION PRESSURE:
$$\begin{array}{r} 997.000 \\ + \quad 14.696 \\ \hline 1011.696 \end{array} = P1$$
 PSIG
3. INITIAL ISOLATION TEMPERATURE:
$$\begin{array}{r} 78.2 \\ + \quad 459.7 \\ \hline 537.9 \end{array} = T1$$
 DEGREES F
4. STOP TIME (TO THE SECOND): 05:10:00 (MINUTES * 60)
ELAPSED TIME IN SECONDS: 900 (PLUS SECONDS) = T
5. FINAL ISOLATION PRESSURE:
$$\begin{array}{r} 991.000 \\ + \quad 14.696 \\ \hline 1005.696 \end{array} = P2$$
 PSIG
6. FINAL ISOLATION TEMPERATURE:
$$\begin{array}{r} 78.0 \\ + \quad 459.7 \\ \hline 537.7 \end{array} = T2$$
 DEGREES F

V = 1.4

CALCULATE THE LEAK RATE PER THE FOLLOWING:

$$\text{LEAK RATE} = \frac{579.478 (1.4)}{T} \quad (P1/T1 - P2/T2)$$

LEAK RATE = 0.0094 SCCS V = 1.4

8.0 LSS ENGINEERING AS-BUILT CONFIGURATION DATA (cont.)

RSRM: 033 BIO: 60 STS: 58

8.19 RH 135 Vent Plug & Leak Check

RH AFT FIELD JOINT 135 DEGREE VENT PORT PLUG LEAK CHECK

| <u>ITEM</u> | <u>PART NO.</u> | <u>SERIAL/LOT NO.</u> |
|-------------------|-----------------|-----------------------|
| GREASE | 1U51916-09 | ECL-0072 |
| PLUG, BOTTOM | 1U76425-01 | ECL-0016 |
| PLUG, TOP | 1U76425-03 | ECL-0021 |
| PLUG, CLOSURE | 1U50159-02 | ECL-0019 |
| O-RING, PRIMARY | 1U50228-44 | ECL-0015 |
| O-RING, SECONDARY | 1U50228-15 | ECL-0121 |
| O-RING, CLOSURE | 1U50228-25 | ECL-0069 |

LEAK TEST DATA

1. START TIME (TO THE SECOND): 03:50:00
2. INITIAL ISOLATION PRESSURE:
$$\begin{array}{r} 994.000 \\ + \quad 14.696 \\ \hline 1008.696 \end{array} = P1$$
 PSIG
3. INITIAL ISOLATION TEMPERATURE:
$$\begin{array}{r} 73.5 \\ + \quad 459.7 \\ \hline 533.2 \end{array} = T1$$
 DEGREES F
4. STOP TIME (TO THE SECOND): 04:05:00 (MINUTES * 60)
ELAPSED TIME IN SECONDS: 900 (PLUS SECONDS) = T
5. FINAL ISOLATION PRESSURE:
$$\begin{array}{r} 989.000 \\ + \quad 14.696 \\ \hline 1003.696 \end{array} = P2$$
 PSIG
6. FINAL ISOLATION TEMPERATURE:
$$\begin{array}{r} 74.0 \\ + \quad 459.7 \\ \hline 533.7 \end{array} = T2$$
 DEGREES F

V = 1.4

CALCULATE THE LEAK RATE PER THE FOLLOWING:

$$\text{LEAK RATE} = \frac{579.478 (1.4)}{T} (P1/T1 - P2/T2)$$

LEAK RATE = 0.0101 SCCS

V = 1.4

8.0 LSS ENGINEERING AS-BUILT CONFIGURATION DATA (cont.)

RSRM: 033 BIO: 60 STS: 58

8.19 RH 135 Vent Plug & Leak Check (continued)

RH CENTER FIELD JOINT 135 DEGREE VENT PORT PLUG LEAK CHECK

| <u>ITEM</u> | <u>PART NO.</u> | <u>SERIAL/LOT NO.</u> |
|-------------------|-----------------|-----------------------|
| GREASE | 1U51916-09 | ECL-0075 |
| PLUG, BOTTOM | 1U76425-01 | ECL-0014 |
| PLUG, TOP | 1U76425-03 | ECL-0021 |
| PLUG, CLOSURE | 1U50159-02 | ECL-0019 |
| O-RING, PRIMARY | 1U50228-44 | ECL-0020 |
| O-RING, SECONDARY | 1U50228-15 | ECL-0121 |
| O-RING, CLOSURE | 1U50228-25 | ECL-0069 |

LEAK TEST DATA

1. START TIME (TO THE SECOND): 08:15:00
2. INITIAL ISOLATION PRESSURE: 993.000 PSIG
+ 14.696
1007.696 = P1
3. INITIAL ISOLATION TEMPERATURE: 74.8 DEGREES F
+ 459.7
534.5 = T1
4. STOP TIME (TO THE SECOND): 08:30:00 (MINUTES * 60)
ELAPSED TIME IN SECONDS: 900 = T (PLUS SECONDS)
5. FINAL ISOLATION PRESSURE: 989.000 PSIG
+ 14.696
1003.696 = P2
6. FINAL ISOLATION TEMPERATURE: 74.9 DEGREES F
+ 459.7
534.6 = T2

V = 1.4

CALCULATE THE LEAK RATE PER THE FOLLOWING:

$$\text{LEAK RATE} = \frac{579.478 (1.4)}{T} (P1/T1 - P2/T2)$$

LEAK RATE = 0.007 SCCS V = 1.4

8.0 LSS ENGINEERING AS-BUILT CONFIGURATION DATA (cont.)

RSRM: 033 BIO: 60 STS: 58

8.19 RH 135 Vent Plug & Leak Check (continued)

RH FORWARD FIELD JOINT 135 DEGREE VENT PORT PLUG LEAK CHECK

| <u>ITEM</u> | <u>PART NO.</u> | <u>SERIAL/LOT NO.</u> |
|-------------------|-----------------|-----------------------|
| GREASE | 1U51916-09 | ECL-0072 |
| PLUG, BOTTOM | 1U76425-01 | ECL-0014 |
| PLUG, TOP | 1U76425-03 | ECL-0021 |
| PLUG, CLOSURE | 1U50159-02 | ECL-0019 |
| O-RING, PRIMARY | 1U50228-44 | ECL-0015 |
| O-RING, SECONDARY | 1U50228-15 | ECL-0121 |
| O-RING, CLOSURE | 1U50228-25 | ECL-0069 |

LEAK TEST DATA

1. START TIME (TO THE SECOND): 02:33:30
2. INITIAL ISOLATION PRESSURE:
$$\begin{array}{r} 995.0 \\ + \quad 14.696 \\ \hline 1009.696 \end{array} = P1$$
 PSIG
3. INITIAL ISOLATION TEMPERATURE:
$$\begin{array}{r} 76.0 \\ + \quad 459.7 \\ \hline 535.7 \end{array} = T1$$
 DEGREES F
4. STOP TIME (TO THE SECOND): 02:48:30 (MINUTES * 60)
ELAPSED TIME IN SECONDS: 900 = T (PLUS SECONDS)
5. FINAL ISOLATION PRESSURE:
$$\begin{array}{r} 992.0 \\ + \quad 14.696 \\ \hline 1006.696 \end{array} = P2$$
 PSIG
6. FINAL ISOLATION TEMPERATURE:
$$\begin{array}{r} 76.0 \\ + \quad 459.7 \\ \hline 535.7 \end{array} = T2$$
 DEGREES F

V = 1.4

CALCULATE THE LEAK RATE PER THE FOLLOWING:

$$\text{LEAK RATE} = \frac{579.478 (1.4)}{T} \quad (P1/T1 - P2/T2)$$

LEAK RATE = 0.0050 SCCS

V = 1.4

8.0 LSS ENGINEERING AS-BUILT CONFIGURATION DATA (cont.)

RSRM: 033 BIO: 60 STS: 58

8.20 LH Field Joint Closeout

AFT FIELD JOINT CLOSEOUT

| <u>ITEM</u> | <u>PART NO.</u> | <u>SERIAL/LOT NO.</u> | <u>DATE</u> |
|----------------|-----------------|-----------------------|-------------|
| JOINT HEATER | 1U77252-01 | 0000139 | 19 MAY 93 |
| SENSOR ASSY | 1U77076-01 | 0000099 | 19 MAY 93 |
| SENSOR ASSY | 1U77076-02 | 0000089 | 19 MAY 93 |
| THERMAL BAR. | 1U77157-01 | ECL-0148 | 19 MAY 93 |
| HEATER STRAP | 1U77114-01 | 0000194 | 19 MAY 93 |
| LINK | 1U77119-01 | 0000179 | 19 MAY 93 |
| CLIP | 1U77120-01 | 0000190 | 19 MAY 93 |
| AFT CORK STRIP | 1U77160-01 | ECL-0122 | 19 MAY 93 |
| FWD CORK STRIP | 1U77160-02 | ECL-0133 | 19 MAY 93 |

REVISION _____

DOC NO TWR-64563 VOL
SEC PAGE 70

8.0 LSS ENGINEERING AS-BUILT CONFIGURATION DATA (cont.)

RSRM: 033 BIO: 60 STS: 58

8.20 LH Field Joint Closeout (continued)

CENTER FIELD JOINT CLOSEOUT

| <u>ITEM</u> | <u>PART NO.</u> | <u>SERIAL/LOT NO.</u> | <u>DATE</u> |
|----------------|-----------------|-----------------------|-------------|
| JOINT HEATER | 1U77252-01 | 0000140 | 19 MAY 93 |
| SENSOR ASSY | 1U77076-01 | 0000094 | 19 MAY 93 |
| SENSOR ASSY | 1U77076-02 | 0000094 | 19 MAY 93 |
| THERMAL BAR. | 1U77157-01 | ECL-0145 | 19 MAY 93 |
| HEATER STRAP | 1U77114-01 | 0000188 | 19 MAY 93 |
| LINK | 1U77119-01 | 0000201 | 19 MAY 93 |
| CLIP | 1U77120-01 | 0000180 | 19 MAY 93 |
| AFT CORK STRIP | 1U77160-01 | ECL-0126 | 20 MAY 93 |
| FWD CORK STRIP | 1U77160-02 | ECL-0115 | 20 MAY 93 |

8.0 LSS ENGINEERING AS-BUILT CONFIGURATION DATA (cont.)

RSRM: 033 BIO: 60 STS: 58

8.20 LH Field Joint Closeout (continued)

FORWARD FIELD JOINT CLOSEOUT

| <u>ITEM</u> | <u>PART NO.</u> | <u>SERIAL/LOT NO.</u> | <u>DATE</u> |
|----------------|-----------------|-----------------------|-------------|
| JOINT HEATER | 1U77252-01 | 0000124 | 21 MAY 93 |
| SENSOR ASSY | 1U77076-01 | 0000095 | 21 MAY 93 |
| SENSOR ASSY | 1U77076-02 | 0000084 | 21 MAY 93 |
| THERMAL BAR. | 1U77157-01 | ECL-0147 | 21 MAY 93 |
| HEATER STRAP | 1U77114-01 | 0000189 | 21 MAY 93 |
| LINK | 1U77119-01 | 0000171 | 21 MAY 93 |
| CLIP | 1U77120-01 | 0000192 | 21 MAY 93 |
| AFT CORK STRIP | 1U77160-01 | ECL-0131 | 22 MAY 93 |
| FWD CORK STRIP | 1U77160-02 | ECL-0126 | 22 MAY 93 |

8.0 LSS ENGINEERING AS-BUILT CONFIGURATION DATA (cont.)

RSRM: 033 BIO: 60 STS: 58

8.21 RH Field Joint Closeout

AFT FIELD JOINT CLOSEOUT

| <u>ITEM</u> | <u>PART NO.</u> | <u>SERIAL/LOT NO.</u> | <u>DATE</u> |
|----------------|-----------------|-----------------------|-------------|
| JOINT HEATER | 1U77252-01 | 0000126 | 22 MAY 93 |
| SENSOR ASSY | 1U77076-01 | 0000103 | 22 MAY 93 |
| SENSOR ASSY | 1U77076-02 | 0000092 | 22 MAY 93 |
| THERMAL BAR. | 1U77157-01 | ECL-0143 | 22 MAY 93 |
| HEATER STRAP | 1U77114-01 | 0000187 | 22 MAY 93 |
| LINK | 1U77119-01 | 0000170 | 22 MAY 93 |
| CLIP | 1U77120-01 | 0000191 | 22 MAY 93 |
| AFT CORK STRIP | 1U77160-01 | ECL-0129 | 27 MAY 93 |
| FWD CORK STRIP | 1U77160-02 | ECL-0114 | 27 MAY 93 |

8.0 LSS ENGINEERING AS-BUILT CONFIGURATION DATA (cont.)

RSRM: 033 BIO: 60 STS: 58

8.21 RH Field Joint Closeout (continued)

CENTER FIELD JOINT CLOSEOUT

| <u>ITEM</u> | <u>PART NO.</u> | <u>SERIAL/LOT NO.</u> | <u>DATE</u> |
|----------------|-----------------|-----------------------|-------------|
| JOINT HEATER | 1U77252-01 | 0000123 | 26 MAY 93 |
| SENSOR ASSY | 1U77076-01 | 0000098 | 26 MAY 93 |
| SENSOR ASSY | 1U77076-02 | 0000090 | 26 MAY 93 |
| THERMAL BAR. | 1U77157-01 | ECL-0146 | 27 MAY 93 |
| HEATER STRAP | 1U77114-01 | 0000181 | 27 MAY 93 |
| LINK | 1U77119-01 | 0000177 | 27 MAY 93 |
| CLIP | 1U77120-01 | 0000193 | 27 MAY 93 |
| AFT CORK STRIP | 1U77160-01 | ECL-0128 | 27 MAY 93 |
| FWD CORK STRIP | 1U77160-02 | ECL-0123 | 27 MAY 93 |

REVISION _____

DOC NO TWR-64563 VOL
SEC PAGE
74

8.0 LSS ENGINEERING AS-BUILT CONFIGURATION DATA (cont.)

RSRM: 033 BIO: 60 STS: 58

8.21 RH Field Joint Closeout (continued)

FORWARD FIELD JOINT CLOSEOUT

| <u>ITEM</u> | <u>PART NO.</u> | <u>SERIAL/LOT NO.</u> | <u>DATE</u> |
|----------------|-----------------|-----------------------|-------------|
| JOINT HEATER | 1U77252-01 | 0000146 | 27 MAY 93 |
| SENSOR ASSY | 1U77076-01 | 0000100 | 27 MAY 93 |
| SENSOR ASSY | 1U77076-02 | 0000091 | 27 MAY 93 |
| THERMAL BAR. | 1U77157-01 | ECL-0144 | 27 MAY 93 |
| HEATER STRAP | 1U77114-01 | 0000193 | 27 MAY 93 |
| LINK | 1U77119-01 | 0000169 | 27 MAY 93 |
| CLIP | 1U77120-01 | 0000148 | 27 MAY 93 |
| AFT CORK STRIP | 1U77160-01 | ECL-0130 | 28 MAY 93 |
| FWD CORK STRIP | 1U77160-02 | ECL-0125 | 28 MAY 93 |

8.0 LSS ENGINEERING AS-BUILT CONFIGURATION DATA (cont.)

RSRM: 033 BIO: 60 STS: 58

8.22 Forward Assembly Installation (LH/RH)

LH DATE: 18 MAY 93

| <u>ITEM</u> | <u>PART NO.</u> | <u>LOT NUMBER</u> | <u>QTY</u> |
|-------------|-----------------|-------------------|------------|
| PINS | 1U51055-03 | ECL-0009 | 195 |

| | | | |
|-------------|------------|-----|-----|
| PINS (ALT.) | 1U51055-09 | N/A | N/A |
|-------------|------------|-----|-----|

| | | | |
|---------------|------------|---------|---|
| STRAPPING KIT | 1U75345-07 | 0000157 | 1 |
|---------------|------------|---------|---|

=====

RH DATE: 26 MAY 93

| <u>ITEM</u> | <u>PART NO.</u> | <u>LOT NUMBER</u> | <u>QTY</u> |
|-------------|-----------------|-------------------|------------|
| PINS | 1U51055-03 | ECL-0003 | 122 |
| | 1U51055-03 | ECL-0005 | 73 |

| | | | |
|-------------|------------|-----|-----|
| PINS (ALT.) | 1U51055-09 | N/A | N/A |
|-------------|------------|-----|-----|

| | | | |
|---------------|------------|---------|---|
| STRAPPING KIT | 1U75345-07 | 0000158 | 1 |
|---------------|------------|---------|---|

8.0 LSS ENGINEERING AS-BUILT CONFIGURATION DATA (cont.)

RSRM: 033 BIO: 60 STS: 58

8.23 LH Safe and Arm Installation

| <u>ITEM</u> | <u>PART NO.</u> | <u>SERIAL/LOT NO.</u> | <u>DATE</u> |
|-------------|-----------------|-----------------------|-------------|
| SAFE & ARM | 1U52295-08 | 0000004 | 15JUN93 |
| GASKET | 1U77464-01 | 0000029 | 15JUN93 |
| BOLTS | 1U51569-02 | ECL-0011 | 15JUN93 |
| WASHER, PLI | 1UMS21206-C6 | ECL-0018 | 15JUN93 |

LEAK CHECK DATA

DATE: 17JUN93

| PRIMARY TO SECONDARY CAVITY | | ALLOWED | ACTUAL RATE |
|-----------------------------------|---------------------------|---------|----------------|
| | 1000 PSIG DECAY LEAK RATE | .10 | 0.001532 SCCS |
| | 30 PSIG DECAY LEAK RATE | .0082 | -0.000043 SCCS |

PRINTOUT PLACED IN DATA BOOK BY: R. C. Hillard

LEAK CHECK PORT PLUG DATA

| <u>ITEM</u> | <u>PART NO.</u> | <u>SERIAL/LOT NO.</u> | <u>DATE</u> |
|-------------|-----------------|-----------------------|-------------|
| O-RING | 1U50228-25 | ECL-0069 | 17JUN93 |
| PLUG | 1U50159-02 | ECL- N/A | 17JUN93 |

PLUG INSTALLATION VERIFIED BY: R. C. Hillard

8.0 LSS ENGINEERING AS-BUILT CONFIGURATION DATA (cont.)

RSRM: 033 BIO: 60 STS: 58

8.24 RH Safe and Arm Installation

| <u>ITEM</u> | <u>PART NO.</u> | <u>SERIAL/LOT NO.</u> | <u>DATE</u> |
|-------------|-----------------|-----------------------|-------------|
| SAFE & ARM | 1U52295-08 | 0000006 | 15JUN93 |
| GASKET | 1U77464-01 | 0000032 | 15JUN93 |
| BOLTS | 1U51569-02 | ECL-0011 | 15JUN93 |
| WASHER, PLI | MS21206-C6 | ECL-0018 | 15JUN93 |

LEAK CHECK DATA

DATE: 17JUN93

| PRIMARY TO SECONDARY CAVITY | | ALLOWED | ACTUAL RATE | |
|-----------------------------------|---------------------------|---------|-------------|------|
| | 1000 PSIG DECAY LEAK RATE | .10 | 0.0004 | SCCS |
| | 30 PSIG DECAY LEAK RATE | .0082 | 0.00005 | SCCS |

PRINTOUT PLACED IN DATA BOOK BY: R. Haskell

LEAK CHECK PORT PLUG DATA

| <u>ITEM</u> | <u>PART NO.</u> | <u>SERIAL/LOT NO.</u> | <u>DATE</u> |
|-------------|-----------------|-----------------------|-------------|
| O-RING | 1U50228-25 | ECL-0069 | 17JUN93 |
| PLUG | 1U50159-02 | ECL- N/A | 17JUN93 |

PLUG INSTALLATION VERIFIED BY: R. Haskell

8.0 LSS ENGINEERING AS-BUILT CONFIGURATION DATA (cont.)

RSRM: 033 BIO: 60 STS: 58

8.25 LH Verification of Leak Check/Vent Port Plug Installation

| <u>ITEM</u> | <u>PHOTO REVIEWED BY</u> <u>FLOW LEAD (INITIALS)</u> | <u>DATE</u> |
|--|---|-------------|
| SAFE & ARM 306 DEG. LK CK PORT PLUG | R. C. Hillard | 13JUL93 |
| FORWARD JOINT 135 DEG. VENT PORT PLUG | R. C. Hillard | 13JUL93 |
| FORWARD JOINT 45 DEG. LK CHECK PORT PLUG | R. C. Hillard | 13JUL93 |
| CENTER JOINT 135 DEG. VENT PORT PLUG | R. C. Hillard | 13JUL93 |
| CENTER JOINT 45 DEG. LK CHECK PORT PLUG | R. C. Hillard | 13JUL93 |
| AFT JOINT 135 DEG. VENT PORT PLUG | R. C. Hillard | 13JUL93 |
| AFT JOINT 45 DEG. LK CHECK PORT PLUG | R. C. Hillard | 13JUL93 |
| AFT EXIT CONE 270 DEG. LEAK CHECK PORT PLUG | R. C. Hillard | 13JUL93 |

8.0 LSS ENGINEERING AS-BUILT CONFIGURATION DATA (cont.)

RSRM: 033 BIO: 60 STS: 58

8.26 RH Verification of Leak Check/Vent Port Plug Installation

| <u>ITEM</u> | <u>PHOTO REVIEWED BY</u> <u>FLOW LEAD (INITIALS)</u> | <u>DATE</u> |
|--|---|-------------|
| SAFE & ARM 306 DEG. LK CK PORT PLUG | R. C. Hillard | 13JUL93 |
| FORWARD JOINT 135 DEG. VENT PORT PLUG | R. C. Hillard | 13JUL93 |
| FORWARD JOINT 45 DEG. LK CHECK PORT PLUG | R. C. Hillard | 13JUL93 |
| CENTER JOINT 135 DEG. VENT PORT PLUG | R. C. Hillard | 13JUL93 |
| CENTER JOINT 45 DEG. LK CHECK PORT PLUG | R. C. Hillard | 13JUL93 |
| AFT JOINT 135 DEG. VENT PORT PLUG | R. C. Hillard | 13JUL93 |
| AFT JOINT 45 DEG. LK CHECK PORT PLUG | R. C. Hillard | 13JUL93 |
| AFT EXIT CONE 270 DEG. LEAK CHECK PORT PLUG | R. C. Hillard | 13JUL93 |

REVISION _____

DOC NO. TWR-64563 | VOL
SEC | PAGE

8.0 LSS ENGINEERING AS-BUILT CONFIGURATION DATA (cont.)

RSRM: 033 BIO: 60 STS: 58

8.27 Roll to Pad Date: 26 June 1993

8.28 Launch Date: 12 September 1993

8.29 Segment Return to Utah:

| | <u>AFT SEG</u> | <u>AFT CTR SEG</u> | <u>FWD CTR SEG</u> | <u>FWD SEG</u> |
|-----------|----------------|--------------------|--------------------|----------------|
| LH: DATE | 4 Oct 1993 | 4 Oct 1993 | 4 Oct 1993 | 4 Oct 1993 |
| R/R CAR # | CSXT 600513 | CSXT 600514 | CSXT 600510 | UP 50027 |
| RH: DATE | 4 Oct 1993 | 4 Oct 1993 | 4 Oct 1993 | 4 Oct 1993 |
| R/R CAR # | UP 50029 | MP 865025 | CSXT 600512 | FEC 101 |

8.30 Exit Cone Return to Utah:

| | | | |
|-----------|--------------|-----------|--------------|
| LH: DATE | 21 Sept 1993 | RH: DATE | 21 Sept 1993 |
| Truck No. | Yowell 5926 | Truck No. | Yowell 5926 |

8.31 Nozzle Return to Utah

| | | | |
|-----------|--------------|-----------|--------------|
| LH: DATE | 22 Sept 1993 | RH: DATE | 22 Sept 1993 |
| Truck No. | Yowell 5946 | Truck No. | Yowell 5926 |

APPENDIX A

Engineering Specifications and Changes

AFT BOOSTER ASSEMBLY DRAWING: 1U76950-03 REVISION: A ECO: 2,3,5,6

RSRM STACKING DRAWING: 1U77426-02 REVISION: A ECO: 6,7

STACKING SPECIFICATION: STW9-3835 REVISION: N SCN: 19

FECs APPLICABLE TO THIS FLOW: RSRM-095

TCTIs APPLICABLE TO THIS FLOW: N/A

BLDG 45s APPLICABLE TO THIS FLOW: N/A

APPENDIX A

Engineering Specifications and Changes (continued)

The following list provides the OMI title, OMI number, and OMI Revision as it applied to RSRM-033 (STS-51):

| <u>OMI Title</u> | <u>OMI No.</u> | <u>OMI Rev.</u> |
|---|----------------|-----------------|
| Stacking and Alignment Operations | B5303 | V |
| SRB System Mate and Closeout | B5304 | N |
| Aft Booster Assembly Electrical Buildup | B5305 | R |
| SRB Ordnance Connection and Pad Closeout | B5306 | K |
| SRB Cable Installation and Checkout and Prepower Electrical Checks | B5307 | Q |
| SRB RPSF Operations | B5308 | P |
| Aft Booster Assembly (RPSF) | B5309 | Q |
| SRB Standard Technical Practices | B5311 | H |

APPENDIX B

Problem Reports (PRs)

The following pages represent Problem Reports (PRs) that were initiated during the operational flow of RSRM-033, STS-51.

PROBLEM REPORT COUNT

RSRM-033
STS-51

| | TOTAL PR'S | SRM ONLY | SRM OPEN | WASATCH RESP. | PRs SENT TO WAS. | TAIR LOG STATUS |
|-------------------------------------|---------------|-------------|-------------|------------------|---------------------|--------------------|
| ----- | ----- | ----- | ----- | ----- | ----- | ----- |
| LEFT | | | | | | |
| ----- | | | | | | |
| SR-LF-60-008 (R&I FORWARD) | 0 | 0 | 0 | 0 | 0 | CLOSED |
| SR-LFC-60-008 (R&I CTR. FORWARD) | 0 | 0 | 0 | 0 | 0 | CLOSED |
| SR-LAC-60-008 (R&I CTR. AFT) | 0 | 0 | 0 | 0 | 0 | CLOSED |
| SR-LA-60-001 (R&I AFT) | 0 | 0 | 0 | 0 | 0 | CLOSED |
| SR-EC-60L-017 (R&I EXIT CONE) | 0 | 0 | 0 | 0 | 0 | CLOSED |
| AB-BI060L (AFT BUILDUP) | 4 | 3 | 0 | 0 | 3 | CLOSED |
| SB-BI060L (ASSEMBLY) | 7 | 4 | 0 | 1 | 4 | |
| RIGHT | | | | | | |
| ----- | | | | | | |
| SR-RF-60-008 (R&I FORWARD) | 0 | 0 | 0 | 0 | 0 | CLOSED |
| SR-RFC-60-008 (R&I CTR. FORWARD) | 0 | 0 | 0 | 0 | 0 | CLOSED |
| SR-RAC-60-008 (R&I CTR. AFT) | 3 | 3 | 0 | 2 | 3 | CLOSED |
| SR-RA-60-001 (R&I AFT) | 0 | 0 | 0 | 0 | 0 | CLOSED |
| SR-EC-60R-018 (R&I EXIT CONE) | 1 | 1 | 0 | 1 | 1 | CLOSED |
| AB-BI060R (AFT BUILDUP) | 7 | 1 | 0 | 1 | 1 | CLOSED |
| SB-BI060R (ASSEMBLY) | 13 | 5 | 0 | 3 | 4 | |
| GENERAL | | | | | | |
| ----- | | | | | | |
| AB-BI060 (AFT BUILDUP) | 0 | 0 | 0 | 0 | 0 | CLOSED |
| SB-BI060 (ASSEMBLY) | 3 | 2 | 0 | 2 | 2 | |
| ----- | | | | | | |
| TOTAL | 38 | 19 | 0 | 10 | 18 | |

NOTE: TOTAL PR'S OPEN (INCLUDING THIOKOL & USBI)= 1

08/19/93 TAIR COUNT AT 0430 HOURS.


PR CLOSURE COUNT IS SUBJECT TO ENGINEERING EVALUATION
AND IS BASED ON THE PREMISE THAT WORK IS 'COMPLETE'.

Thiokol LSS Quality Engineering


TWR-64563

B2

WASATCH/SPC PR TRENDS



WASATCH PRs




OPEN CAARS

| FLIGHT | CAAR NUMBER | CAR NUMBER | DATE ISSUED | DAYS OPEN | RESP. ORGAN. |
|----------|----------------|---------------|----------------|--------------|-----------------|
| RSRM-023 | PV6249287CT1 | | 07/29/93 | 21 | WASATCH |


CAAR DATA

| ACTIVITY | TOTAL CAAR'S | OPEN CAAR'S |
|---------------|--------------|-------------|
| RSRM-029 | 0 | 0 |
| RSRM-030 | 1 | 0 |
| RSRM-031 | 1 | 0 |
| RSRM-032 | 1 | 0 |
| RSRM-033 | 2 | 0 |
| RSRM-034 | 0 | 0 |
| RSRM-035 | 2 | 0 |
| MISCELLANEOUS | 11 | 0 |


VAB & RPSF PR TREND




RESPONSIBILITY BREAKDOWN




DISCREPANCY BREAKDOWN



PR SMRB ASSESSMENT



PR TREND



ASSEMBLY DATA

| FLIGHT | TOTAL PR'S | SRM PR'S | CLOSED PR'S |
|----------|------------|----------|-------------|
| <hr/> | | | |
| RSRM-021 | 31 | 14 | 14 |
| RSRM-022 | 41 | 14 | 14 |
| RSRM-024 | 45 | 18 | 18 |
| RSRM-025 | 53 | 19 | 19 |
| RSRM-026 | 49 | 20 | 20 |
| RSRM-027 | 37 | 16 | 16 |
| RSRM-028 | 64 | 25 | 25 |
| RSRM-029 | 46 | 18 | 18 |
| RSRM-030 | 46 | 20 | 20 |
| RSRM-031 | 34 | 13 | 13 |
| RSRM-032 | 46 | 17 | 17 |
| RSRM-033 | 38 | 19 | 19 |
| RSRM-034 | 29 | 17 | 17 |
| RSRM-035 | 19 | 9 | 9 |
| RSRM-023 | 7 | 6 | 2 |







APPENDIX C

The Motor Set Status can be found on the following page.

MOTOR SET STATUS

AS OF 13 SEPTEMBER 1993

STS-51 BI060 360T033

| A (11) | B (11) | ON DOCK KSC | OFF LOAD | RECEIVING INSPECTION | LOCATION | JMATE | LEAK CHECK | HEATER INSTALL | JOINT CLOSEOUT | CABLE INSTALL | HEATER CHECKOUT |
|---|--------|-------------|-----------|----------------------|----------|-------|------------|----------------|----------------|---------------|-----------------|
|  0000004 0000006 | A | 16 MAR 93 | | 14 APR 93 | PAD | A | 17 JUN 93 | | | | |
| | B | 16 MAR 93 | | 14 APR 93 | PAD | B | 17 JUN 93 | | | | |
|  41H5 26R1 | A | 1 MAR 93 | 15 MAR 93 | 16 MAR 93 | PAD | A | 19 MAY 93 | 21 MAY 93 | 25 MAY 93 | 28 MAY 93 | 28 MAY 93 |
| | B | 9 MAR 93 | 22 MAR 93 | 24 MAR 93 | PAD | B | 27 MAY 93 | 27 MAY 93 | 1 JUN 93 | 4 JUN 93 | 7 JUN 93 |
|  95R2 80 | A | 1 MAR 93 | 17 MAR 93 | 17 MAR 93 | PAD | A | 17 MAY 93 | 19 MAY 93 | 22 MAY 93 | 28 MAY 93 | 28 MAY 93 |
| | B | 9 MAR 93 | 26 MAR 93 | 30 MAR 93 | PAD | B | 25 MAY 93 | 26 MAY 93 | 28 MAY 93 | 4 JUN 93 | 7 JUN 93 |
|  9R5 79 | A | 1 MAR 93 | 19 MAR 93 | 23 MAR 93 | PAD | A | 15 MAY 93 | 19 MAY 93 | 26 MAY 93 | 28 MAY 93 | 28 MAY 93 |
| | B | 9 MAR 93 | 29 MAR 93 | 23 MAR 93 | PAD | B | 21 MAY 93 | 22 MAY 93 | 28 MAY 93 | 4 JUN 93 | 7 JUN 93 |
|  40R2 863 31 20R3 | A | 8 FEB 93 | 12 FEB 93 | 17 FEB 93 | PAD | A | 25 FEB 93 | 25 FEB 93 | 25 FEB 93 | 25 FEB 93 | 25 FEB 93 |
| | B | 1 MAR 93 | 8 FEB 93 | 9 MAR 93 | PAD | B | 4 MAR 93 | 4 MAR 93 | 4 MAR 93 | 4 MAR 93 | 4 MAR 93 |
|  47R3 43R3 | A | 23 FEB 93 | | | | A | 10 MAY 93 | | | | |
| | B | 9 MAR 93 | | | | B | 17 MAY 93 | | | | |

Legend

- ON DOCK KSC -- RAILCARS PHYSICALLY ON KSC
- OFFLOAD -- SEGMENT LIFTED FROM THE RAILCAR
- REC / INSP -- COMPLETE WHEN WEATHER COVER INST
- AFT BOOSTER ON MLP -- LAST PIN INSTALLED
- AEC MATED -- LAST BOLT TORQUED
- LEAK CHECK -- VENT AND LK OK PLUGS INSTALLED
- HEATER INSTALL -- HEATER INSTALLED ON SEGMENT
- CABLE INSTALL -- ALL HEATER CABLES CONNECTED
- JOINT CLOSEOUT -- ALL JPS PAINT TOP COAT INSTALL
- ION COMPLETE
- HEATER CHECKOUT, FIELD JOINT AND IGNITER -- B5307
- TASK 5 COMPLETED
- FORWARD ASSEMBLY MATE -- LAST PIN INSTALLED
- ET / SRB MATE -- BEAM DISCONNECTED FROM ET
- ORBITER MATE -- BEAM DISCONNECTED FROM ORBITER
- ROLL TO PAD -- FIRST MOTION IN THE VAB
- FWD SKT CLOSEOUT -- FORWARD SKIRT DOOR INST



Launch 12 SEPT 93

FORWARD ASSEMBLY MATE LH 18 MAY 93 RH 1 JUN 93

ET/SRB MATE 2 JUN 93 ORBITER MATE 19 JUN 93

ROLL TO PAD 26 JUN 93 FWD SKT CLOSEOUT L/H 2 SEPT 93 R/H 2 SEPT 93

C-2

TWR-64563

C2

DN22 (0) (2)
TURNER J/PUBLICATION
MARSHALL SPACE FLIGHT CENTER
HUNTSVILLE AL.

DELETIONS OR CHANGES 544-4494
RETURN ADDRESS DN22D 000002444